

Appendix C Nozzle PFORs

Final Postflight Hardware Evaluation Report RSRM-29 (STS-54)

September 1993

Prepared for:

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION
GEORGE C. MARSHALL SPACE FLIGHT CENTER
MARSHALL SPACE FLIGHT CENTER, ALABAMA 35812

Contract No.	NAS8-38100
DR No.	4-23
WBS No.	4C601-04-01
ECS No.	SS4772

Thiokol CORPORATION
SPACE OPERATIONS

P.O. Box 707, Brigham City, Utah 84302-0707 (801) 863-3511

(NASA-CR-193894) POSTFLIGHT
HARDWARE EVALUATION RSRM-29
(STS-54). APPENDIX C: NOZZLE PFORs
Final Report (Thiokol Corp.) 86 p

N94-24064

Unclass

NOZZLE REQUIRED EVALUATION FORMS LIST

<u>PFOR #</u>	<u>Title</u>	<u>Side</u>	<u>Joint, Part, or Location</u>	<u>Final Report Page Number</u>
C-1	Nozzle Assembly Quick-look Condition	Left	N/A	C-1
C-2	Internal Nozzle Joint Condition	Left	Joint #2	C-2
C-3	Nose Inlet-to-Flex Bearing-to-Cowl Joint Condition Drawing Worksheet	Left	Joint #2	C-3
C-2	Internal Nozzle Joint Condition	Left	Joint #3	C-4
C-4	Nose Inlet-to-Throat Joint Condition Drawing Worksheet	Left	Joint #3	C-5
C-2	Internal Nozzle Joint Condition	Left	Joint #4	C-6
C-5	Throat-to-Forward Exit Cone Joint Condition Drawing Worksheet	Left	Joint #4	C-7
C-2	Internal Nozzle Joint Condition	Left	Joint #5	C-8
C-6	Aft End Ring-to-Fixed Housing Joint Condition Drawing Worksheet	Left	Joint #5	C-9
C-7	Cowl Insulation Segment Condition	Left	Cowl	C-10
C-8	Flexible Bearing, Flexible Bearing Protector, and Flexible Boot Condition	Left	Flexible Bearing, Protector, & Boot	C-11
C-9	Flexible Bearing Protector Thickness Measurements	Left	Flexible Bearing Protector	C-12
C-10	Throat Diameter Measurements (Data Collection Only)	Left	Throat	C-13
C-11	Outer Boot Ring Char and Erosion Measurements and Flexible Boot Condition	Left	Outer Boot Ring & Flexible Boot	C-14
C-12	Nozzle Subassembly Phenolic Bondline Condition	Left	Aft Exit Cone	C-15
C-12	Nozzle Subassembly Phenolic Bondline Condition	Left	Forward Exit Cone	C-16

(Note: Clarification PFORs will be inserted after the applicable required PFOR in the Final Report and will have the same page number as the required PFOR appended by a sequential alphabetic extension.)

NOZZLE REQUIRED EVALUATION FORMS LIST (Cont.)

<u>PFOR #</u>	<u>Title</u>	<u>Side</u>	<u>Joint, Part, or Location</u>	<u>Final Report Page Number</u>
C-12	Nozzle Subassembly Phenolic Bondline Condition	Left	Throat	C-17
C-12	Nozzle Subassembly Phenolic Bondline Condition	Left	Aft Inlet/ Forward Nose Rings	C-18
C-12	Nozzle Subassembly Phenolic Bondline Condition	Left	Nose Cap	C-19
C-12	Nozzle Subassembly Phenolic Bondline Condition	Left	Cowl	C-20
C-12	Nozzle Subassembly Phenolic Bondline Condition	Left	Fixed Housing	C-21
C-13	Cowl Ring Phenolic (CCP) Section Condition	Left	Cowl	C-22
C-14	Forward Exit Cone Phenolic (CCP) Section Condition	Left	Forward Exit Cone	C-23
C-15	Fixed Housing Phenolic (CCP) Section Condition	Left	Fixed Housing	C-24
C-16	Throat Inlet Assembly Phenolic (CCP) Section Condition	Left	Throat	C-25
C-17	Nose Cap Phenolic (CCP) Section Condition	Left	Nose Cap	C-26
C-18	Forward Nose Ring and Aft Inlet Ring Phenolic (CCP) Section Condition	Left	Forward Nose & Aft Inlet Rings	C-27
C-1	Nozzle Assembly Quick-look Condition	Right	N/A	C-28
C-2	Internal Nozzle Joint Condition	Right	Joint #2	C-29
C-3	Nose Inlet-to-Flex Bearing-to-Cowl Joint Condition Drawing Worksheet	Right	Joint #2	C-30
C-2	Internal Nozzle Joint Condition	Right	Joint #3	C-31
C-4	Nose Inlet-to-Throat Joint Condition Drawing Worksheet	Right	Joint #3	C-32

(Note: Clarification PFORs will be inserted after the applicable required PFOR in the Final Report and will have the same page number as the required PFOR appended by a sequential alphabetic extension.)

NOZZLE REQUIRED EVALUATION FORMS LIST (Cont.)

<u>PFOR #</u>	<u>Title</u>	<u>Side</u>	<u>Joint, Part, or Location</u>	<u>Final Report Page Number</u>
C-2	Internal Nozzle Joint Condition	Right	Joint #4	C-33
C-5	Throat-to-Forward Exit Cone Joint Condition Drawing Worksheet	Right	Joint #4	C-34
C-2	Internal Nozzle Joint Condition	Right	Joint #5	C-35
C-6	Aft End Ring-to-Fixed Housing Joint Condition Drawing Worksheet	Right	Joint #5	C-36
C-7	Cowl Insulation Segment Condition	Right	Cowl	C-37
C-8	Flexible Bearing, Flexible Bearing Protector, and Flexible Boot Condition	Right	Flexible Bearing, Protector, & Boot	C-38
C-9	Flexible Bearing Protector Thickness Measurements	Right	Flexible Bearing Protector	C-39
C-10	Throat Diameter Measurements (Data Collection Only)	Right	Throat	C-40
C-11	Outer Boot Ring Char and Erosion Measurements and Flexible Boot Condition	Right	Outer Boot Ring & Flexible Boot	C-41
C-12	Nozzle Subassembly Phenolic Bondline Condition	Right	Aft Exit Cone	C-42
C-12	Nozzle Subassembly Phenolic Bondline Condition	Right	Forward Exit Cone	C-43
C-12	Nozzle Subassembly Phenolic Bondline Condition	Right	Throat	C-44
C-12	Nozzle Subassembly Phenolic Bondline Condition	Right	Aft Inlet/ Forward Nose Rings	C-45
C-12	Nozzle Subassembly Phenolic Bondline Condition	Right	Nose Cap	C-46
C-12	Nozzle Subassembly Phenolic Bondline Condition	Right	Cowl	C-47
C-12	Nozzle Subassembly Phenolic Bondline Condition	Right	Fixed Housing	C-48

(Note: Clarification PFORs will be inserted after the applicable required PFOR in the Final Report and will have the same page number as the required PFOR appended by a sequential alphabetic extension.)

NOZZLE REQUIRED EVALUATION FORMS LIST (Cont.)

<u>PFOR #</u>	<u>Title</u>	<u>Side</u>	<u>Joint, Part, or Location</u>	<u>Final Report Page Number</u>
C-13	Cowl Ring Phenolic (CCP) Section Condition	Right	Cowl	C-49
C-14	Forward Exit Cone Phenolic (CCP) Section Condition	Right	Forward Exit Cone	C-50
C-15	Fixed Housing Phenolic (CCP) Section Condition	Right	Fixed Housing	C-51
C-16	Throat Inlet Assembly Phenolic (CCP) Section Condition	Right	Throat	C-52
C-17	Nose Cap Phenolic (CCP) Section Condition	Right	Nose Cap	C-53
C-18	Forward Nose Ring and Aft Inlet Ring Phenolic (CCP) Section Condition	Right	Forward Nose & Aft Inlet Rings	C-54

(Note: Clarification PFORs will be inserted after the applicable required PFOR in the Final Report and will have the same page number as the required PFOR appended by a sequential alphabetic extension.)

POSTFLIGHT OBSERVATION RECORD (PFOR) C-1
Nozzle Assembly Quick-look Condition

Motor No.: 360L029	Side: Left (A)	Date: 1/25/95																
Assessment Engineer(s)/Inspector(s): C. Quick																		
<p>Nozzle Assembly Quick-look Observations:</p> <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 60%;"></th> <th style="width: 10%; text-align: center;">Yes</th> <th style="width: 10%; text-align: center;">No</th> <th style="width: 20%; text-align: center;">Comment #</th> </tr> </thead> <tbody> <tr> <td>A. Metal Damage Due to Transportation or Handling?</td> <td style="text-align: center;">_____</td> <td style="text-align: center;">✓</td> <td style="text-align: center;">_____</td> </tr> <tr> <td>B. Phenolic Damage Due to Transportation or Handling?</td> <td style="text-align: center;">_____</td> <td style="text-align: center;">✓</td> <td style="text-align: center;">_____</td> </tr> <tr> <td>C. Foreign Material?</td> <td style="text-align: center;">_____</td> <td style="text-align: center;">✓</td> <td style="text-align: center;">_____</td> </tr> </tbody> </table>				Yes	No	Comment #	A. Metal Damage Due to Transportation or Handling?	_____	✓	_____	B. Phenolic Damage Due to Transportation or Handling?	_____	✓	_____	C. Foreign Material?	_____	✓	_____
	Yes	No	Comment #															
A. Metal Damage Due to Transportation or Handling?	_____	✓	_____															
B. Phenolic Damage Due to Transportation or Handling?	_____	✓	_____															
C. Foreign Material?	_____	✓	_____															
<p>Notes / Comments</p> <p>NOZZLE ASSEMBLY SECURED ON OD OF FIXED HSG FLANGE FROM 150°-225°: 300°-305°</p> <p>NO NOZZLE MOVEMENT ON CHAINS</p> <p>NO INSURED FIGHTER IN TIME</p> <p>NOZZLE DOUBLE WRAPPED IN PLASTIC</p>																		
<p>Preliminary PFAR(s)? _____ Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Preliminary PFAR Number(s): _____</p> <p>Clarification Form(s)? _____ Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Clarification Form Page No.(s): _____</p>																		

POSTFLIGHT OBSERVATION RECORD (PFOR) C-2
Internal Nozzle Joint Condition

Motor No.: 360L029	Side: Left (A)	Date: 1/23/98																																																																												
Assessment Engineer(s)/Inspector(s): R. Quick T. FRESTON																																																																														
Joint: Nose Inlet-to-Flex Bearing-to-Cowl (Joint #2)																																																																														
<p>Internal Nozzle Joint Observations:</p> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:60%;"></th> <th style="width:10%;">Yes</th> <th style="width:10%;">No</th> <th style="width:20%;">Comment #</th> </tr> </thead> <tbody> <tr><td>A. Gas Penetration in the RTV (Terminated, Through)?</td><td style="text-align:center">✓</td><td></td><td></td></tr> <tr><td>B. RTV Not Below Char Line?</td><td></td><td style="text-align:center">✓</td><td></td></tr> <tr><td>C. RTV To the Primary O-ring?</td><td></td><td style="text-align:center">✓</td><td></td></tr> <tr><td>D. RTV Past the Primary O-ring?</td><td></td><td style="text-align:center">✓</td><td></td></tr> <tr><td>E. Uncured RTV?</td><td></td><td style="text-align:center">✓</td><td></td></tr> <tr><td>F. Voids Within RTV?</td><td></td><td style="text-align:center">✓</td><td></td></tr> <tr><td>G. Foreign Material?</td><td></td><td style="text-align:center">✓</td><td></td></tr> <tr><td>H. Heat Affected or Eroded Virgin CCP, GCP/SCP, or adhesive?</td><td></td><td style="text-align:center">✓</td><td></td></tr> <tr><td>I. Damaged Phenolics?</td><td></td><td style="text-align:center">✓</td><td></td></tr> <tr><td>J. Bondline Edge Separations? Use Clarification Form.</td><td></td><td style="text-align:center">✓</td><td></td></tr> <tr><td>K. Phenolics Axially Displaced From Housing?</td><td></td><td style="text-align:center">✓</td><td></td></tr> <tr><td>L. Heat Affected Metal?</td><td></td><td style="text-align:center">✓</td><td></td></tr> <tr><td>M. Unbonded or Blistered Paint?</td><td style="text-align:center">✓</td><td></td><td>See R. C-2</td></tr> <tr><td>N. Corrosion?</td><td></td><td></td><td></td></tr> <tr><td>O. Excessive Grease in Threaded Bolt Holes?</td><td></td><td style="text-align:center">✓</td><td></td></tr> <tr><td>P. Bolt Hole Damage (Through, Threaded/Helical Coil Insert)?</td><td></td><td style="text-align:center">✓</td><td></td></tr> <tr><td>Q. Bent or Broken Bolts?</td><td></td><td style="text-align:center">✓</td><td></td></tr> <tr><td>R. Metal Damage (Joints or Housings)?</td><td></td><td style="text-align:center">✓</td><td></td></tr> </tbody> </table>				Yes	No	Comment #	A. Gas Penetration in the RTV (Terminated, Through)?	✓			B. RTV Not Below Char Line?		✓		C. RTV To the Primary O-ring?		✓		D. RTV Past the Primary O-ring?		✓		E. Uncured RTV?		✓		F. Voids Within RTV?		✓		G. Foreign Material?		✓		H. Heat Affected or Eroded Virgin CCP, GCP/SCP, or adhesive?		✓		I. Damaged Phenolics?		✓		J. Bondline Edge Separations? Use Clarification Form.		✓		K. Phenolics Axially Displaced From Housing?		✓		L. Heat Affected Metal?		✓		M. Unbonded or Blistered Paint?	✓		See R. C-2	N. Corrosion?				O. Excessive Grease in Threaded Bolt Holes?		✓		P. Bolt Hole Damage (Through, Threaded/Helical Coil Insert)?		✓		Q. Bent or Broken Bolts?		✓		R. Metal Damage (Joints or Housings)?		✓	
	Yes	No	Comment #																																																																											
A. Gas Penetration in the RTV (Terminated, Through)?	✓																																																																													
B. RTV Not Below Char Line?		✓																																																																												
C. RTV To the Primary O-ring?		✓																																																																												
D. RTV Past the Primary O-ring?		✓																																																																												
E. Uncured RTV?		✓																																																																												
F. Voids Within RTV?		✓																																																																												
G. Foreign Material?		✓																																																																												
H. Heat Affected or Eroded Virgin CCP, GCP/SCP, or adhesive?		✓																																																																												
I. Damaged Phenolics?		✓																																																																												
J. Bondline Edge Separations? Use Clarification Form.		✓																																																																												
K. Phenolics Axially Displaced From Housing?		✓																																																																												
L. Heat Affected Metal?		✓																																																																												
M. Unbonded or Blistered Paint?	✓		See R. C-2																																																																											
N. Corrosion?																																																																														
O. Excessive Grease in Threaded Bolt Holes?		✓																																																																												
P. Bolt Hole Damage (Through, Threaded/Helical Coil Insert)?		✓																																																																												
Q. Bent or Broken Bolts?		✓																																																																												
R. Metal Damage (Joints or Housings)?		✓																																																																												
<p>Notes / Comments</p> <p>1- GAS PATH TERMINATED AT NOSE INLET HSG/FWD END RING AT 310° SOGT EXTEND TO PRIMARY O-RING</p>																																																																														
<p>Preliminary PFAR(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Preliminary PFAR Number(s): _____</p> <p>Clarification Form(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Clarification Form Page No.(s): _____</p>																																																																														

POSTFLIGHT OBSERVATION RECORD (PFOR) C-3

Nose Inlet-to-Flex Bearing-to-Cowl Joint (Joint #2) Condition Drawing Worksheet

Motor No.: 360L029


Side: Left (A)

Date: 1/28/93

Assessment Engineer(s)/Inspector(s): R. QUICK T. FRESTON

Sketch Observations Below (include locations and sizes of sketched features):

- (32)
- 1-BUBBLED PAINT ON FWD FACE OF FLEX BEARING INTERMITTENT FROM 0°-180°
 - 2-INTERMITTENT MISSING PAINT ON FLANGE OF FWD END RING 360°



3-SOOT AND OD BRG FLANGE AT 310°

4-1/2" EXCESS GREASE IN HOUSING

5-GREASE COVERAGE WAS NOMINAL

6-SOOT ON AFT FACE OF NOSE INLET HOUSING SEE PG B-12

7-TYPICAL RTV BEAD 913 INTERMIXING 560°

8-LIGHT CORROSION CORROSION INTERMITTENT 360°

ORIGINAL PAGE IS OF POOR QUALITY

Classification Form(s)? ☐ Yes ☒ No

Clarification Form Page No. (s):

POSTFLIGHT OBSERVATION RECORD (PFOR) C-2
Internal Nozzle Joint Condition

Motor No.: 360L029	Side: Left (A)	Date: 1-28-93
Assessment Engineer(s)/Inspector(s): L.E. WILKES / T. FRESTON		
Joint: Nose Inlet-to-Throat (Joint #3)		

Internal Nozzle Joint Observations:	Yes	No	Comment #
A. Gas Penetration in the RTV (Terminated, Through)?		✓	
B. RTV Not Below Char Line?		✓	
C. RTV To the Primary O-ring?		✓	
D. RTV Past the Primary O-ring?		✓	
E. Uncured RTV?		✓	
F. Voids Within RTV?		✓	
G. Grease Inhibiting RTV Backfill?		✓	
H. Foreign Material?		✓	
I. Heat Affected or Eroded Virgin CCP, GCP/SCP, or adhesive?		✓	
J. Damaged Phenolics?		✓	
K. Bondline Edge Separations? Use Clarification Form.	✓		1
L. Phenolics Axially Displaced From Housing?		✓	
M. Heat Affected Metal?		✓	
N. Unbonded or Blistered Paint?		✓	
O. Corrosion?	✓		2
P. Alignment Pin Damage?		✓	3
Q. Excessive Grease in Threaded Bolt Holes?		✓	
R. Bolt Hole Damage (Through, Threaded/Helical Coil Insert)?		✓	
S. Bent or Broken Bolts?		✓	
T. Metal Damage (Joints or Housings)?		✓	

Notes / Comments

① SEE PFOR CLARIFICATION FORM PAGE C-4A

② TYPICAL LIGHT-TO-MEDIUM CORROSION AT METAL-TO-ADHESIVE INTERFACE AROUND FULL CIRCUMFERENCE ON THROAT & NOSE ASSYS.

③ NO ALIGNMENT PIN DAMAGE OR PIN HOLE DAMAGE ON THROAT NOSE OR BEARING FWD END RING.

ORIGINAL PAGE IS
OF POOR QUALITY

Preliminary PFAR(s)?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Preliminary PFAR Number(s):
Clarification Form(s)?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Clarification Form Page No. (s): C-4A

POSTFLIGHT OBSERVATION RECORD (PFOR) C-4
Nose Inlet-to-Throat Joint (Joint #3) Condition Drawing Worksheet

Motor No.: 360L029


Side: Left (A)

Date: 1-28-93

Assessment Engineer(s)/Inspector(s): L.E. WILKES

Sketch Observations Below (Include locations and sizes of sketched features):

RTV BELOW CHAR LINE
BEHIND AROUND CIRCUM.
EXCEPT AT 350° OVER
THIS DISTANCE, RTV
TAPERED BACK TO
POINT MAX CIRCUM
WITH 1.5 IN



• LIGHT-TO-MEDIUM AL. OXIDE
CORROSION AROUND FULL
CIRCUMFERENCE
• NO BOLT HOLE OR HORIZONTAL
CRACK DAMAGE

• TYPICAL LIGHT COAT OF GREASE
OVER FULL FLANGE JOINT METAL SURF
THROAT & NOSE HOUSINGS
• LIGHT-TO-MEDIUM RUST CORROSION
AROUND FULL CIRCUMFERENCE
HEAVY RUST STAINS ON PHENOLIC
SURFACE 330°-360° AND INTERMITTENT
AROUND REMAINING CIRCUMFERENCE
• TYPICAL INTERM. METAL-TO-ADHESIVE
SEPARATIONS ON THROAT ONLY.

Clarification Form(s)? ☐ Yes ☒ No

Clarification Form Page No. (s):

REVISION _____

DOC NO. TWR-64222
SEC

VOL
PAGE C-5

ORIGINAL PAGE IS
OF POOR QUALITY

POSTFLIGHT OBSERVATION RECORD (PFOR) C-2
Internal Nozzle Joint Condition

Motor No.: 360L029	Side: Left (A)	Date: 4/26/93
Assessment Engineer(s)/Inspector(s): R. Quick		
Joint: Throat-to-Forward Exit Cone (Joint #4)		

Internal Nozzle Joint Observations:	Yes	No	Comment #
A. Gas Penetration in the RTV (Terminated, Through)?		<input checked="" type="checkbox"/>	
B. RTV Not Below Char Line?		<input checked="" type="checkbox"/>	
C. RTV To the Primary O-ring?	<input checked="" type="checkbox"/>		SEE PG 7
D. RTV Past the Primary O-ring?		<input checked="" type="checkbox"/>	
E. Uncured RTV?		<input checked="" type="checkbox"/>	
F. Voids Within RTV?		<input checked="" type="checkbox"/>	
G. Grease Inhibiting RTV Backfill?		<input checked="" type="checkbox"/>	
H. Foreign Material?		<input checked="" type="checkbox"/>	
I. Heat Affected or Eroded Virgin CCP, GCP/SCP, or adhesive?		<input checked="" type="checkbox"/>	
J. Damaged Phenolics?		<input checked="" type="checkbox"/>	
K. Bondline Edge Separations? Use Clarification Form.	<input checked="" type="checkbox"/>		SEE PG C-6A
L. Phenolics Axially Displaced From Housing?		<input checked="" type="checkbox"/>	
M. Heat Affected Metal?		<input checked="" type="checkbox"/>	
N. Unbonded or Blistered Paint?		<input checked="" type="checkbox"/>	
O. Corrosion?	<input checked="" type="checkbox"/>		1 =
P. Alignment Pin Damage?		<input checked="" type="checkbox"/>	
Q. Excessive Grease in Threaded Bolt Holes?		<input checked="" type="checkbox"/>	
R. Bolt Hole Damage (Through, Threaded/Helical Coil Insert)?		<input checked="" type="checkbox"/>	
S. Bent or Broken Bolts?		<input checked="" type="checkbox"/>	
T. Metal Damage (Joints or Housings)?		<input checked="" type="checkbox"/>	

Notes / Comments

HEAVY CORROSION INTERMITTENT FULL CIRCUMFERENCE IN
 AREA OF HEAVY CORROSION INTERMITTENT FULL CIRCUMFERENCE IN
 AREA OF HEAVY CORROSION INTERMITTENT FULL CIRCUMFERENCE IN
 AREA OF HEAVY CORROSION INTERMITTENT FULL CIRCUMFERENCE IN

OF POOR QUALITY

Primary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s):


Clarification Form(s)? ☐ Yes ☒ No Clarification Form Page No.(s): C-6A

POSTFLIGHT OBSERVATION RECORD (PFOR) C-5
Throat-to-Forward Exit Cone Joint (Joint #4) Condition Drawing Worksheet

Motor No.: 360L029	Side: Left (A)	Date: 1/26/93
Assessment Engineer(s)/Inspector(s): R. QUICK		

Sketch Observations Below (include locations and sizes of sketched features):

*ACTV BELOW DARK LINE
5000
5000
00-35° E 142° 150° 035°
310°-335°
③ NO EXCESS GREASE IN
BOLT HOLES*



*4 SEPARATION BETWEEN
FIBER GLASS & ADHESIVE
TO GCP*

*6 GREASE COVERAGE
WAS NOMINAL*

*5 PHENOLIC DISCOLORED
APPEARS TO BE RUST
FROM 310 THRU 3 TO 35°*

Clarification Form(s)? ☐ Yes ☒ No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-2
Internal Nozzle Joint Condition

Motor No.: 360L029	Side: Left (A)	Date: 27 JAN 1993
Assessment Engineer(s)/Inspector(s): <u>Jim PASSMAN, TREY FRESTON</u>		

Joint: Aft End Ring-to-Fixed Housing (Joint #5)

Internal Nozzle Joint Observations:	Yes	No	Comment #
A. Gas Penetration in the RTV (Terminated, Through)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
B. RTV Not Below Char Line?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
C. RTV To the Primary O-ring?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	①
D. RTV Past the Primary O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
E. Uncured RTV?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
F. Voids Within RTV?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	②
G. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
H. Heat Affected or Eroded Virgin CCP, GCP/SCP, or adhesive?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
I. Damaged Phenolics?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
J. Bondline Edge Separations? Use Clarification Form.	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
K. Phenolics Axially Displaced From Housing?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
L. Heat Affected Metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
M. Unbonded or Blistered Paint?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
N. Corrosion?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	③
O. Alignment Pin Damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
P. Excessive Grease in Threaded Bolt Holes?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Q. Bolt Hole Damage (Through, Threaded/Helical Coil Insert)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
R. Bent or Broken Bolts?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
S. Metal Damage (Joints or Housings)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments

① RTV TO PRIMARY O-RING AT 50°-107°, 225°-230°; AND 248°-245°.

② Void in RTV LOCATED AT 157°-160° 1.9" CIRC. x 0.18" WIDE.
Void in RTV LOCATED AT 177°-179° 1.3" CIRC. x 0.25" WIDE.
Small voids 0.10"-0.25" DIAMETER INTERMITTENT 360°.

③ CORROSION AS NOTED ON PFOR C-6 (PAGE C-9).

Special Issue 3.3.10 No abnormal erosion patterns or propagation of the gauges was observed

Preliminary PFAR(s)?	Yes	<input checked="" type="checkbox"/> No	Preliminary PFAR Number(s):
Clarification Form(s)?	Yes	<input checked="" type="checkbox"/> No	Clarification Form Page No.(s):

POSTFLIGHT OBSERVATION RECORD (PFOR) C-6
Aft End Ring-to-Fixed Housing Joint (Joint #5) Condition Drawing Worksheet

Motor No.: 360L029


Side: Left (A)

Date: 27 JAN 1993

Assessment Engineer(s)/Inspector(s): JIM PASSMAN, TREVOR FRESTON

Sketch Observations Below (include locations and sizes of sketched features):

- ① ~~Light~~ to MEDIUM CORROSION INTERMITTENT 360°.
- ② NOMINAL GREASE COVERAGE.
- ③ RTV to PRIMARY 50°-107°, 225°-230°, and 240°-245°.



Clarification Form(s)? ☐ Yes ☒ No Clarification Form Page No.(s):

POSTFLIGHT OBSERVATION RECORD (PFOR) C-8
Flexible Bearing, Flexible Bearing Protector, and Flexible Boot Condition

Motor No.: 360L029	Side: Left (A)	Date: 27 Jan 1993
Assessment Engineer(s)/Inspector(s): <u>JIM PASSMAN, TREUD FRESTON, WILKES</u>		
Flexible Bearing, Bearing Protector, and Boot Observations:		
	Yes	No
A. Bearing Protector Burn-Through?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
B. Cracks Through the Bearing Protector?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
C. Bearing Protector Heat Effects or Erosion Other Than at Cowl Vent Hole Locations?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
D. Soot Between the Bearing Protector and Flexible Bearing?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
E. Heat Effects to the Flexible Bearing?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
F. Bent or Broken Bearing Protector Bolts?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
G. Flexible Boot Burn-Through?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
H. Abnormal Heat Effects or Erosion to Flexible Boot ID?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
I. Foreign Material in Boot Cavity?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
		Comment #
		①
		③
		②

Notes / Comments

- ① Small AREA OF EROSION ON FLEX BEARING PROTECTOR 2.8" AFT OF BELLY BAND IN LINE WITH VENT HOLE AT 50°. AREA MEASURES 3.6" CIRC. X 0.95" AXIAL WITH AN APPROXIMATE DEPTH OF 0.025"-0.050". SLAG DEPOSITS WERE FOUND IN CAVITY NEXT TO BEARING PROTECTOR AND COWL INSULATION. EROSION APPEARS TO BE CAUSED BY SLAG. SIMILAR CONDITIONS HAVE BEEN FOUND ON PREVIOUS FLIGHTS.
- ② MIRROR IMAGE OF BEARING PROTECTOR EROSION FOUND ON ID OF BOOT MEASURING 3.7" CIRC. X 1/16" ~~WIDE~~ WIDE, AND APPROX. 0.050" DEEP.
- ③ FWD B/L PROTECTOR SCREW AT 33° SHOWED SMALL (0.070 IN DIA) AREA OF BLACK CORROSION ON SIDE OF SCREW HEAD. SCREW WILL BE EVALUATED FOR POSSIBLE HEAT EFFECTS.

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): _____

Clarification Form(s)? ☒ Yes ☐ No Clarification Form Page No.(s): C11A

Flexible Boot Cavity Clarification Form

Motor No.: 360L029


Side: ☒ Left (A) ☐ Right (B)

Date: 27 JAN 1993

Assessment Engineer(s)/Inspector(s): JIM PASSMAN, TREVOR FRESTON

Description: EROSION ON BEARING PROTECTOR AND FLEX BOOT ID AT 50° VENT HOLE

Sketch Observations Below (include locations and sizes of sketched features):



AREA OF EROSION LOCATED DIRECTLY IN LINE WITH 50° VENT HOLE.
APPEARS TO BE CAUSED BY SLAG.

NOTE: DIMENSIONS NOT TO SCALE

Corresponding Comment Number(s): ①, ②

REVISION _____

DOC NO. TWR-64222
SEC _____

VOL _____

PAGE C-11A

Thiokol CORPORATION

SPACE OPERATIONS

POSTFLIGHT OBSERVATION RECORD (PFOR) C-9
Flexible Bearing Protector Thickness Measurements

Motor No.: 360L029


Side: Left (A)

Date: 12-02-73

Assessment Engineer(s)/Inspector(s): R. MASTERS, M. E. RUTEE JR

Record the Flexible Bearing Protector Gas Impingement Area Thickness Measurements (see figure) Below:

Degree Location	Thickness Measurement "A" (inches)	Degree Location	Thickness Measurement "A" (inches)	Degree Location	Thickness Measurement "A" (inches)
0	.713	120	.718	240	.711
10	.693	130	.728	250	.697
20	.715	140	.698	260	.765
30	.694	150	.705	270	.726
40	.719	160	.696	280	.716
50	.722	170	.708	290	.726
60	.724	180	.709	300	.712
70	.698	190	.726	310	.693
80	.695	200	.724	320	.713
90	.698	210	.724	330	.692
100	.734	220	.725	340	.693
110	.716	230	.718	350	.692



* "A" is the minimum thickness of the bearing protector in-line with the cowl vent holes. It corresponds to the deepest gas impingement location.

Notes / Comments

Preliminary PFAR(s)? ☐ Yes ☒ No

Preliminary PFAR Number(s):

Clarification Form(s)? ☐ Yes ☒ No

Clarification Form Page No.(s)

ORIGINAL PAGE IS
OF POOR QUALITY

REVISION

DOC NO. TWR-64222 VOL
SEC PAGE C-12

POSTFLIGHT OBSERVATION RECORD (PFOR) C-10
Throat Diameter Measurements (Data Collection Only)

Motor No.: 360L029	Side: Left (A)	Date: 01 - 28 - 93
--------------------	----------------	--------------------

Assessment Engineer(s)/Inspector(s): RR GALLAGOS, Ted BENSON

Record the Nozzle Throat Diameter Measurements Below:

Degree Location	Diameter Measurement (inches)
0	<u>55.977"</u>
45	<u>56.000"</u>
90	<u>55.935"</u>
135	<u>56.000"</u>

Notes / Comments

SL-45062

Clarification Form(s)? ☐ Yes ☒ No Clarification Form Page No.(s): _____

REVISION _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-11

Outer Boot Ring Char and Erosion Measurements and Flexible Boot Condition

Motor No.: 360L029 Side: Left (A) Date: 3/3/93, 2-17-93

Assessment Engineer(s)/Inspector(s): Jim PASSMAN, MARK CLARK

Flexible Boot/Outer Boot Ring Separation Observations: Yes No Comment #
A. Heat Effects in Boot/OBR Separation? ✓

Record the Outer Boot Ring Char and Erosion Measurements Below:

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
8.0	<u>0.08</u>	<u>0.94</u>	<u>—</u>	<u>1.01*</u>	<u>0.08</u>	<u>0.96</u>	<u>—</u>	<u>0.96*</u>
9.0	<u>0.09</u>	<u>0.91</u>	<u>0.12</u>	<u>0.83</u>	<u>0.09</u>	<u>0.88</u>	<u>—</u>	<u>0.88*</u>
10.0	<u>0.15</u>	<u>0.88</u>	<u>0.09</u>	<u>0.87</u>	<u>0.12</u>	<u>0.86</u>	<u>0.06</u>	<u>0.80</u>
11.3	<u>0.24</u>	<u>0.82</u>	<u>0.07</u>	<u>0.94</u>	<u>0.16</u>	<u>0.95</u>	<u>.08</u>	<u>0.82</u>

Negative Margin of Safety? Yes ✓ No Station: Degree:

Record the Number of Plies Remaining on the Flexible Boot:

Degree	Plies
Location	Remaining
0	<u>3.7</u>
90	<u>3.3</u>
180	<u>3.9</u>
270	<u>3.4</u>

Negative Margin of Safety? Yes ✓ No Degree:

Notes / Comments

* TOTAL (CHAR AND EROSION)

Special Issue 3.3.10

No abnormal erosion patterns or propagation observed
not separating within boot plies

Preliminary PFAR(s)? Yes ✓ No

Preliminary PFAR Number(s):

Clarification Form(s)? Yes ✓ No

Clarification Form Page No.(s):

ORIGINAL PAGE IS
OF POOR QUALITY

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360L029	Side: Left (A)	Date: 2-4-93
Assessment Engineer(s)/Inspector(s): WILKES / TELLETS / J. PASSMAN / P. MILLER		
Phenolic Subassembly: Aft Exit Cone Assembly		

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	45-135	135-225	225-315	315-45				
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								
Within GCP	100	100	100	100				
GCP-to-CCP								
Within CCP								

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
	45-135	135-225	225-315	315-45				
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP	100	100	100	100				

Phenolic Removal Method: HAMMER, WEDGE & PEEL, MUCK WORK.

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
C. Corrosion?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
D. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
E. Voids in Polysulfide (Aft Exit Cone Polysulfide Groove)?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(1)

Notes / Comments

(1) VOIDS INTERMITTENT ON INBOARD SURFACE; TYPICAL SIZE 0.05" - 0.10" DIA.

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): _____

Clarification Form(s)? ☐ Yes ☒ No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360L029	Side: Left (A)	Date: 1-29-93
Assessment Engineer(s)/Inspector(s): WILKES/FRESTON/LAURE/SIMMONS/1011		
Phenolic Subassembly: Forward Exit Cone Assembly		

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

SEE NOTE 1

	Degree Location				
	0-90	90-180	180-270	270-360	total
Metal-to-Adhesive	15	10	15	15	14
Within Adhesive	10	10	10	10	10
Adhesive-to-GCP	75	80	75	75	76
Within GCP					
GCP-to-CCP					
Within CCP					

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

N.A.

	Degree Location				
	0-90	90-180	180-270	270-360	total
Metal-to-Adhesive					
Within Adhesive					
Adhesive-to-GCP					

Phenolic Removal Method: _____

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?		<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input checked="" type="checkbox"/>		2
C. Corrosion?	<input checked="" type="checkbox"/>		3
D. Foreign Material?		<input checked="" type="checkbox"/>	

Notes / Comments: ① SEE CLARIFICATION FORM PAGE C-16A FOR DEVIATIONS FROM TYPICAL PHENOLIC LINER REMOVAL PROCEDURES.
② SEE TWR CLARIFICATION FORM PAGE C-16B.
③ TYPICAL MED.-TO-HEAVY CORROSION BETWEEN 6-TO-10 INCHES OF FWD END AROUND 75% OF CIRCUMFERENCE AND 0-8 INCHES INTERN. TYPICALLY AROUND 10% OF CIRCUMFERENCE AND AROUND ALL SHEARIN HOLES FWD & AFT.

Primary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): _____
Clarification Form(s)? ☒ Yes ☐ No Clarification Form Page No.(s): C-16A & B

ORIGINAL OF POOR QUALITY

General Hardware Clarification Form

Motor No.: 360L029

Side: ☒ Left (A) ☐ Right (B)

Date: 1-29-93

Assessment Engineer(s)/Inspector(s): WILKES/FRESTON/LANGE/SIMMONS/MILLER

Description: PHENOLIC BONDLINE CONDITION, FWD EXIT CONE ASSEMBLY

Sketch Observations Below (include locations and sizes of sketched features):

THE NORMAL PROCEDURE OF PHENOLIC REMOVAL IS TO WATER-
LIFT CUT 4 PLACES 90° APART OVER FULL AXIAL LENGTH THROUGH-
OUT TO METAL SURFACE. NYLON WEDGES ARE THEN DRIVEN
WITH PNEUMATIC HAMMERS, BETWEEN THE METAL AND ADHESIVE. THE
PRIMARY BOND FAILURE MODE IS DETERMINED FROM REMAINING
FRACTIONS OF ADHESIVE.

THE KSM-29A NOZZLE FORWARD EXIT CONE HAD TEN INCHES
OF CCP LAYER REMAINING ON THE FORWARD END, APPROX. FULL
CIRCUMFERENCE AND UP TO EIGHT INCHES MAXIMUM WIDE AXIALLY,
FROM 160° TO 330°. THE REMAINING MIDDLE SECTION SHOWED CCP-TO-
GCP INTERFACES. AN AXIAL SAW CUT WAS MADE THROUGH THE CCP
TO GCP INTERFACE. NYLON WEDGES WERE DRIVEN BETWEEN
THE CCP AND GCP. THE AFT CCP FRAGMENT SEPARATED AT
CCP/GCP INTERFACE. THE FWD FRAGMENT AFT HALF, UP TO SHEATH
SCREWS, SEPARATED AT CCP-TO-GCP INTERFACE. THE REMAINING
FWD FRAGMENT, FROM SHEATH SCREWS FWD, SEPARATED 85%
ADHESIVE-TO-GCP, 10% METAL-TO-ADHESIVE AND 5% WITHIN ADHESIVE.
50% OF THE METAL-TO-ADHESIVE WAS FROM PATCHES AROUND 75% OF THE
SHEATH PIN HELDS. LARGEST PATCH WAS 2.0 IN DIAMETER.

ORIGINAL COPY IS
OF POOR QUALITY

Corresponding Comment Number(s): 1

Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: 360L029	Side: <input checked="" type="checkbox"/> Left (A) <input type="checkbox"/> Right (B)	Date: 2-2-93
Assessment Engineer(s)/Inspector(s): WILKES / MILLER		
Nozzle Subassembly: FWD EXIT CONE		

Record Bondline Adhesive Void Measurements and Locations Below:

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd	Distance From Aft
17	.70	.40		7.4
6	.90	.60		29.4
77	.60	.40		29.2
209	.50	.40		28.6

Notes / Comments ① VERY FEW SMALL ADHESIVE VOIDS WERE OBSERVED
EXCLUSIVELY AROUND CIRCUMFERENCE.

Corresponding Comment Number(s): 2

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360L029	Side: Left (A)	Date: 29 JAN 1993
Assessment Engineer(s)/Inspector(s): <u>JIM PASSMAN, TREVOR FRESTON</u>		
Phenolic Subassembly: Throat Assembly		

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	45°-135°	135°-225°	225°-315°	315°-45°				
Metal-to-Adhesive	100	100	100	100				
Within Adhesive								
Adhesive-to-GCP								
Within GCP								
GCP-to-CCP								
Within CCP								

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								

Phenolic Removal Method: _____

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(1)
C. Corrosion?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(2)
D. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments

- (1) Small Voids Typically 0.10"-0.20" DIA LOCATED INTERMITTENTLY 360°. LARGER VOIDS LOCATED NEAR THE AFT END OF THE 225°-315° SECTION. SIZES AND LOCATIONS ARE DOCUMENTED OF CLARIFICATION FORM PAGE C-17A.
- (2) MEDIUM TO HEAVY CORROSION OVER WHOLE HOUSING BONDLINE SURFACE.

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): _____

Clarification Form(s)? ☒ Yes ☐ No Clarification Form Page No.(s): C-17A

Nozzle Subassembly Bondline Adhesive Void Clarification Form

[illegible]

Corresponding Comment Number(s): (1)

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360L029	Side: Left (A)	Date: 2-1-73
Assessment Engineer(s)/Inspector(s): M. Clark, R. T. Hays		
Phenolic Subassembly: Aft Inlet/Forward Nose Rings		

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	315-45	45-135	135-225	225-315				total
Metal-to-Adhesive	90	100	99	75				91
Within Adhesive	1			2				1
Adhesive-to-GCP	9		2	23				8
Within GCP								
GCP-to-CCP								
Within CCP								

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								

Phenolic Removal Method: _____

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?		<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input checked="" type="checkbox"/>		1
C. Corrosion?	<input checked="" type="checkbox"/>		2
D. Foreign Material?		<input checked="" type="checkbox"/>	

Notes / Comments

2) Medium Corrosion observed in areas of metal-to-adhesive separation

Special Issue 3.3.6

Adhesive void found at 78° measured 0.5" axial x 0.25" circ., 0.35" from tip end of -503 ring

Special Issue 3.3.11

6 voids found greater than 0.30" found see page C-18A. No Repair areas observed on housing

Primary PFAR(s)? ☒ Yes ☐ No

Preliminary PFAR Number(s): _____

Clarification Form(s)? ☒ Yes ☐ No

Clarification Form Page No.(s): C-18A

Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: 360L029	Side: <input checked="" type="checkbox"/> Left (A) <input type="checkbox"/> Right (B)	Date: 2-1-93
Assessment Engineer(s)/Inspector(s): M.E. Clark		
Nozzle Subassembly: -503(Full Loss) King		

Record Bondline Adhesive Void Measurements and Locations Below:

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd	Distance From Aft
274	.11	.21	2.4	
255.5	.40	.15	0.5	
254	.40	.20	0.4	
245	.45	.20	0.8	
227	.30	.20	2.3	
78	.15	.25	0.35	

Notes / Comments

ORIGINAL PAGE IS
OF HIGH QUALITY
ORIGINAL PAGES
COE OF HIGH QUALITY

Corresponding Comment Number(s): 2

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360L029	Side: Left (A)	Date: 2-1-93
Assessment Engineer(s)/Inspector(s): M. Clark, R. Tellers		
Phenolic Subassembly: Nose Cap		

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

Degree Location

	315-45	45-135	135-225	225-315				TOTAL
* Metal-to-Adhesive	3	2	7	1				2
Within Adhesive								
Adhesive-to-GCP								
Within GCP	1	1	1	1				1
GCP-to-CCP	76	97	98	98				97
Within CCP								

* on fuel line only

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

Degree Location

	315-45	45-135	135-225	225-315				TOTAL
Metal-to-Adhesive	30	40	25	20				29
Within Adhesive								
Adhesive-to-GCP	70	60	75	80				71

Phenolic Removal Method: Wedges & hand peel

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
C. Corrosion?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	2
D. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments

Special Issue 3.3.3

No sign of LDI found

Special Issue 3.3.11

2 voids greater than 0.30" found see page C-17A
No repair areas observed on bonding

Imaginary PFAR(s)? ☒ Yes ☐ No

Preliminary PFAR Number(s): 54C-01

Clarification Form(s)? ☒ Yes ☐ No

Clarification Form Page No.(s): C-17A

Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: 360L029	Side: <input checked="" type="checkbox"/> Left (A) <input type="checkbox"/> Right (B)	Date: 2-1-73
Assessment Engineer(s)/Inspector(s): M. Clark, R. Tellers		
Nozzle Subassembly: Nose Cap		

Record Bondline Adhesive Void Measurements and Locations Below:

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd	Distance From Aft
74.5	.40	.20		2.25
30.1	.30	.15	4.80	

Notes / Comments

ORIGINAL PAGE IS
OF POOR QUALITY

Corresponding Comment Number(s): 2

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360L029	Side: Left (A)	Date: 1-28-93
Assessment Engineer(s)/Inspector(s): WILKES / TELLEPS		
Phenolic Subassembly: Cowl Assembly		

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	0-30							
Metal-to-Adhesive	99							
Within Adhesive								
Adhesive-to-SCP	1 *							
Within SCP								
SCP-to-CCP								
Within CCP								

* ABOVE SPRING PINS ONLY

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-SCP								

Phenolic Removal Method: _____

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	1
B. Voids in Adhesive?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	2
C. Corrosion?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
D. Foreign Material?	<input type="checkbox"/>	<input type="checkbox"/>	

**ORIGINAL PAGE IS
OF POOR QUALITY**

Notes / Comments ① SEE PFOR CLARIFICATION FORM PAGE C-20A & B.

② LIGHT TO MEDIUM AL OXIDE CORROSION THROUGHOUT LENGTH & CIRCUMFERENCE OF COWL HOUSING.

Special Issue 3.3.11

1.0 REMAINING AREAS WERE OBSERVED ON COWL HOUSING.

2.0 SET PAGE C-20A & B FOR VOIDS

3.0 SURFACE LAYER OF RTI SQUEEZED BETWEEN METAL HOUSING AND ADHESIVE UP TO 0.001" FROM END FILL CHAMFER AT 232°-310° AND 16 OTHER PLACES. THIS WAS AROUND COWL VERY SLIGHT. NO ADHESIVE VOIDS WERE OBSERVED IN THESE AREAS.

Preliminary PFAR(s)? ☒ Yes ☐ No Preliminary PFAR Number(s): _____

Clarification Form(s)? ☒ Yes ☐ No Clarification Form Page No.(s): C-20A, B

Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: 360L029	Side: <input checked="" type="checkbox"/> Left (A) <input type="checkbox"/> Right (B)	Date: 1-28-93
Assessment Engineer(s)/Inspector(s): WILKES / TELLEPS		
Nozzle Subassembly: COWL		
Record Bondline Adhesive Void Measurements and Locations Below:		
Degree Location	Void Size	Location on Bonding Surface
	Axial	Distance From Fwd CHAIN EDGE
	Circ.	Distance From Aft
156°	0.30	0.10
158°	0.30	0.15
161°	0.10	0.35
162°-167°	0.30	3.95
164°	0.30	0.15
167°	0.40	0.15
167.2°	0.30	0.15
167°	.30	.10
173°	.40	.10
175°	.40	.10
175-176.5°	.25	1.50
176.5°	.45	.10
177°	.30	.20

Notes / Comments MANY SMALL ADHESIVE VOIDS, 0.25 IN. DIA MAX., WERE OBSERVED FROM 140° TO 220°. VERY FEW VOIDS WERE OBSERVED AROUND REMAINING CIRCUMFERENCE.

Corresponding Comment Number(s): 1

Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: 360L029	Side: <input checked="" type="checkbox"/> Left (A) <input type="checkbox"/> Right (B)	Date: 1-28-93
Assessment Engineer(s)/Inspector(s): WILKES / TELLEY'S		
Nozzle Subassembly: COWL		

Record Bondline Adhesive Void Measurements and Locations Below:

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd	Distance From Aft
181	.30	.10	.95	
184-183	.45	1.20	2.20	
184	.30	.25	1.95	
186	.30	.30	1.95	
188	.35	.20	1.65	
192	.35	.05	0.10	
193-194	.20	1.10	.25	
193-201	.30	2.0	.20	
201-202	.25	.70	0.00	
201	.45	.20	0.50	
201	0.10	.35	3.00	

Notes / Comments

ORIGINAL PAGE IS
OF POOR QUALITY

Corresponding Comment Number(s): 1

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360L029	Side: Left (A)	Date: 2 FEB 93
Assessment Engineer(s)/Inspector(s): R. QUICK T. FRESTON		
Phenolic Subassembly: Fixed Housing Assembly		

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location								
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0	
Metal-to-Adhesive	50%	97%	30%	90%	70%	98%	100%	100%	(1)
Within Adhesive									
Adhesive-to-GCP									
Within GCP									
GCP-to-CCP	50%	3%	70%	10%	30%	2%	0%	0%	
Within CCP									

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
	0-360							
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP	100%							

Phenolic Removal Method: _____

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?		<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input checked="" type="checkbox"/>		SEE Pg C-21A
C. Corrosion?		<input checked="" type="checkbox"/>	
D. Foreign Material?		<input checked="" type="checkbox"/>	

Notes / Comments 1 - 80% ADHESIVE TO METAL FAILURE OVER ENTIRE BONDLINE

Preliminary PFAR(s)? ☒ Yes ☐ No Preliminary PFAR Number(s): 54C-02

Clarification Form(s)? ☒ Yes ☐ No Clarification Form Page No.(s): C-21A

Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: 360L029	Side: <input checked="" type="checkbox"/> Left (A) <input type="checkbox"/> Right (B)	Date: 2 FEB 93
Assessment Engineer(s)/Inspector(s): R. QUICK T. FEESTON		
Nozzle Subassembly: FIXED HOUSING ASSEMBLY		

Record Bondline Adhesive Void Measurements and Locations Below:

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd	Distance From Aft
<u>104</u>	<u>.48</u>	<u>.28 overall .55</u>	<u>4.75</u>	<u> </u>
<u>257</u>	<u>1.42</u>	<u>.31</u>	<u> </u>	<u>11.45</u>
<u>260</u>	<u>.40</u>	<u>.53</u>	<u> </u>	<u>5.62</u>
<u>280</u>	<u>.96</u>	<u>.20</u>	<u> </u>	<u>4.85</u>
<u>295</u>	<u>.47</u>	<u>.25</u>	<u> </u>	<u>14.10</u>
<u>65</u>	<u>.53</u>	<u>.35</u>	<u> </u>	<u>8.10</u>
<u>98</u>	<u>.97</u>	<u>.40</u>	<u> </u>	<u>1.05</u>
<u>101</u>	<u>1.10</u>	<u>.27</u>	<u> </u>	<u>1.80</u>
<u>120</u>	<u>.30</u>	<u>.50</u>	<u> </u>	<u>1.70</u>

Notes / Comments

Corresponding Comment Number(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-13
Cowl Ring Phenolic (CCP) Section Condition

Motor No.: 360L029	Side: Left (A)	Date: 5-17-93
--------------------	----------------	---------------

Assessment Engineer(s)/Inspector(s): R. Quirk

Cowl Phenolic Section Observations:

- A. Cross-ply cracking in virgin material?
B. Ply lifting?

Yes	No	Comment #
<u> </u>	<u> ✓ </u>	<u> </u>
<u> </u>	<u> ✓ </u>	<u> </u>

Record the Cowl Char and Erosion Measurements Below:

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
0.3	<u>.30</u>	<u>.56</u>	<u>.26</u>	<u>.57</u>	<u>.30</u>	<u>.52</u>	<u>.27</u>	<u>.51</u>
1.0	<u>.31</u>	<u>.54</u>	<u>.30</u>	<u>.55</u>	<u>.35</u>	<u>.53</u>	<u>.35</u>	<u>.54</u>
2.0	<u>.42</u>	<u>.56</u>	<u>.27</u>	<u>.58</u>	<u>.38</u>	<u>.54</u>	<u>.37</u>	<u>.51</u>
3.0	<u>.45</u>	<u>.62</u>	<u>.32</u>	<u>.63</u>	<u>.35</u>	<u>.63</u>	<u>.36</u>	<u>.61</u>
4.0	<u>.42</u>	<u>.60</u>	<u>.32</u>	<u>.61</u>	<u>.35</u>	<u>.66</u>	<u>.37</u>	<u>.57</u>
5.0	<u>.44</u>	<u>.62</u>	<u>.32</u>	<u>.70</u>	<u>.36</u>	<u>.68</u>	<u>.37</u>	<u>.67</u>
6.0	<u>.47</u>	<u>.70</u>	<u>.22</u>	<u>.74</u>	<u>.25</u>	<u>.79</u>	<u>.25</u>	<u>.61</u>
6.8	<u>0.32</u>	<u>0.73</u>	<u>0.24</u>	<u>0.83</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>

Negative Margin of Safety? Yes ✓ No Station: Degree:

Notes / Comments

Preliminary PFAR(s)? Yes ✓ No Preliminary PFAR Number(s):
Clarification Form(s)? Yes ✓ No Clarification Form Page No.(s):

ORIGINAL PAGE IS
OF POOR QUALITY

POSTFLIGHT OBSERVATION RECORD (PFOR) C-14
Forward Exit Cone Phenolic (CCP) Section Condition

Motor No.: 360L029	Side: Left (A)	Date: 6-10-93
--------------------	----------------	---------------

Assessment Engineer(s)/Inspector(s): M. Clark

Forward Exit Cone Phenolic Section Observations:

	Yes	No	Comment #
A. Cross-ply cracking in virgin material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
B. Ply lifting?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Record the Forward Exit Cone Char and Erosion Measurements Below:

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
1.0	.39	.65	.40	.63	.44	.65	.41	.66
4.0	.42	.65	.41	.62	.40	.63	.39	.77
4.6	.39	.67	.37	.64	.40	.64	.43	.67
8.0	.37	.68	.32	.66	.39	.63	.32	.77
12.0	NA	NA	NA	NA	NA	NA	NA	NA
16.0	↑	↑	↑	↑	↑	↑	↑	↑
20.0	↓	↓	↓	↓	↓	↓	↓	↓
24.0			↓	↓	NA	NA	NA	NA
28.0			NA	NA	.24	.64	.24	.69
32.0			.22	.65	.25	.56	.19	.70
32.9	↓	↓	.22	.61	.19	.62	.15	.75
34.0	NA	NA	.17	.62	.11	.69	.16	.70

Negative Margin of Safety? ☐ Yes ☒ No Station: Degree:

Notes / Comments

CRACKING OF POOR QUALITY

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s):

Clarification Form(s)? ☒ Yes ☐ No Clarification Form Page No.(s): C-23A, C-23B

POSTFLIGHT OBSERVATION RECORD (PFOR) C-19
Forward Exit Cone Phenolic (CCP) Section Condition

Motor No.: 360L029 Side: LEFT (A) Date: 4-9-93

Assessment Engineer(s)/Inspector(s): L.E. WILKES

AFT Exit Cone Phenolic Section Observations:

A. Cross-ply cracking in virgin material?

Yes

No

Comment #

B. Ply lifting?

Record the Forward Exit Cone Char and Erosion Measurements Below:

Station	270°		280°		290°		300°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
118.77	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
113.77	<u>.170</u>	<u>.590</u>	<u>.170</u>	<u>.540</u>	<u>.150</u>	<u>.570</u>	<u>.170</u>	<u>.540</u>
107.77	<u>.150</u>	<u>.580</u>	<u>.170</u>	<u>.520</u>	<u>.150</u>	<u>.560</u>	<u>.150</u>	<u>.570</u>
101.77	<u>.160</u>	<u>.570</u>	<u>.170</u>	<u>.550</u>	<u>.130</u>	<u>.540</u>	<u>.140</u>	<u>.550</u>
95.77	<u>.130</u>	<u>.520</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
89.77	<u>NA</u>	<u>NA</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>
83.77	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>
77.77	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>
73.77	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>

Negative Margin of Safety? Yes ☒ No Station: Degree:

Notes / Comments

Preliminary PFAR(s)? Yes ☒ No Preliminary PFAR Number(s):

Clarification Form(s)? Yes ☒ No Clarification Form Page No.(s):

POSTFLIGHT OBSERVATION RECORD (PFOR) C-19
Forward Exit Cone Phenolic (CCP) Section Condition

Motor No.: 360L029 Side: LEFT(A) Date: 4-9-93

Assessment Engineer(s)/Inspector(s): L.E. WILKES

AFT Exit Cone Phenolic Section Observations:

A. Cross-ply cracking in virgin material?

Yes

No

Comment #

B. Ply lifting?

Record the Forward Exit Cone Char and Erosion Measurements Below:

Station	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
		310°						
118.77	<u>NA</u>	<u>NA</u>						
113.77	<u>.240</u>	<u>.570</u>						
107.77	<u>.130</u>	<u>.670</u>						
101.77	<u>.130</u>	<u>.610</u>						
95.77	<u>NA</u>	<u>NA</u>						
89.77								
83.77								
77.77								
73.77								

Negative Margin of Safety? Yes ☒ No Station: Degree:

Notes / Comments

Preliminary PFAR(s)? Yes ☒ No Preliminary PFAR Number(s):

Clarification Form(s)? Yes ☒ No Clarification Form Page No.(s):

POSTFLIGHT OBSERVATION RECORD (PFOR) C-15
Fixed Housing Phenolic (CCP) Section Condition

Motor No.: 360L029	Side: Left (A)	Date: 6-10-93
--------------------	----------------	---------------

Assessment Engineer(s)/Inspector(s): M. Clark

Fixed Housing Phenolic Section Observations:

	Yes	No	Comment #
A. Cross-ply cracking in virgin material?	<u> </u>	<u> ✓ </u>	<u> </u>
B. Ply lifting?	<u> </u>	<u> ✓ </u>	<u> </u>

Record the Fixed Housing Char and Erosion Measurements Below:

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
0.0	<u>0</u>	<u>1.13</u>	<u>.14</u>	<u>1.30</u>	<u>.07</u>	<u>1.42</u>	<u>1</u>	<u>1.19</u>
1.0	<u>.04</u>	<u>.74</u>	<u>.07</u>	<u>1.02</u>	<u>.08</u>	<u>1.01</u>	<u>0</u>	<u>.91</u>
2.0	<u>0</u>	<u>.85</u>	<u>0</u>	<u>.90</u>	<u>.07</u>	<u>.87</u>	<u>0</u>	<u>1.06</u>
3.0	<u>0</u>	<u>.83</u>	<u>0</u>	<u>1.65</u>	<u>.07</u>	<u>.87</u>	<u>0</u>	<u>1.01</u>
4.0	<u>0</u>	<u>.78</u>	<u>0</u>	<u>1.63</u>	<u>.09</u>	<u>.90</u>	<u>0</u>	<u>.97</u>
5.0	<u>0</u>	<u>.87</u>	<u>0</u>	<u>1.64</u>	<u>.18</u>	<u>.74</u>	<u>0</u>	<u>.93</u>
6.0	<u>0</u>	<u>.88</u>	<u>0</u>	<u>1.60</u>	<u>.04</u>	<u>.86</u>	<u>0</u>	<u>.96</u>
7.0	<u>0</u>	<u>.90</u>	<u>0</u>	<u>1.55</u>	<u>0</u>	<u>.88</u>	<u>0</u>	<u>.76</u>
8.0	<u>0</u>	<u>1.17</u>	<u>0</u>	<u>1.45</u>	<u>0</u>	<u>.83</u>	<u>0</u>	<u>.72</u>
9.0	<u>0</u>	<u>1.63</u>	<u>0</u>	<u>1.64</u>	<u>0</u>	<u>.90</u>	<u>0</u>	<u>1.0</u>
10.75	<u>0</u>	<u>1.91</u>	<u>0</u>	<u>1.66</u>	<u>.15</u>	<u>1.77</u>	<u>0</u>	<u>1.92</u>

Negative Margin of Safety? Yes ✓ No Station: Degree:

Notes / Comments

Preliminary PFAR(s)? Yes ✓ No Preliminary PFAR Number(s):

Clarification Form(s)? Yes ✓ No Clarification Form Page No. (s):

THIS PAGE IS
OF POOR QUALITY

POSTFLIGHT OBSERVATION RECORD (PFOR) C-16
Throat Inlet Assembly Phenolic (CCP) Section Condition

Motor No.: 360L029 Side: Left (A) Date: 3/3/93

Assessment Engineer(s)/Inspector(s): JIM PASSMAN, LARRY WILKS

Throat Inlet Assembly Phenolic Section Observations:

- A. Cross-ply cracking in virgin material?
B. Ply lifting?

Yes No Comment #
____ ✓ ____
____ ✓ ____

Record the Throat Inlet Ring and Throat Ring Char and Erosion Measurements Below:

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
1.0	1.09	0.59	1.08	0.59	1.06	0.47	1.06	0.58
2.0	1.14	0.57	1.09	0.58	1.09	0.54	1.09	0.59
4.0	1.17	0.60	1.14	0.62	1.16	0.57	1.16	0.57
6.0	1.21	0.67	1.19	0.60	1.19	0.62	1.23	0.57
8.0	1.29	0.56	1.22	0.58	1.26	0.47	1.28	0.51
10.0	1.24	0.55	1.19	0.46	1.21	0.48	1.21	0.54
12.0	1.20	0.57	1.13	0.46	1.18	0.54	1.18	0.59
14.0	1.20	0.53	1.10	0.48	1.17	0.53	1.18	0.51
16.0	1.14	0.57	1.04	0.48	1.06	0.57	1.10	0.53
18.0	0.99	0.56	0.91	0.55	0.92	0.46	0.98	0.62
20.0	0.77	0.62	0.68	0.66	0.76	0.61	0.74	0.63
22.0	0.57	0.71	0.48	0.73	0.53	0.77	0.53	0.68
23.0	0.45	0.77	0.43	0.76	0.43	0.71	0.48	0.66

Negative Margin of Safety? Yes No Station: Degree:

Notes / Comments

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s):
Clarification Form(s)? Yes No Clarification Form Page No.(s):

POSTFLIGHT OBSERVATION RECORD (PFOR) C-17
Nose Cap Phenolic (CCP) Section Condition

Motor No.: 360L029	Side: Left (A)	Date: 3/3/93
Assessment Engineer(s)/Inspector(s): Jim Passman, Larry Wilkins		

Nose Cap Phenolic Section Observations:

Yes	No	Comment #
_____	<input checked="" type="checkbox"/>	_____
_____	<input checked="" type="checkbox"/>	_____

A. Cross-ply cracking in virgin material?

B. Ply lifting?

Record the Nose Cap Char and Erosion Measurements Below:

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
1.5	NA	NA	NA	NA	NA	NA	NA	NA
4.0	0.42	0.48	0.34	0.56	0.32	0.54	0.39	0.52
6.0	0.41	0.53	0.35	0.55	0.32	0.52	0.41	0.57
8.0	0.47	0.56	0.42	0.50	0.39	0.53	0.43	0.51
10.0	0.49	0.54	0.44	0.46	0.41	0.55	0.47	0.47
12.0	0.59	0.52	0.47	0.49	0.51	0.49	0.55	0.46
14.0	0.67	0.45	0.49	0.48	0.53	0.47	0.59	0.43
16.0	0.76	0.47	0.60	0.47	0.63	0.45	0.70	0.42
18.0	0.94	0.52	0.74	0.36	0.81	0.47	0.88	0.50
20.0	1.23	0.50	1.08	0.33	0.99	0.45	1.07	0.49
22.0	1.78	0.64	1.54	0.63	1.37	0.61	1.61	0.74
24.0	1.92	0.67	1.68	0.71	1.54	0.72	1.83	0.65
26.0	1.36	0.64	1.18	0.74	1.08	0.76	1.29	0.70

Negative Margin of Safety? _____ Yes ☒ No _____ Station: _____ Degree: _____

Notes / Comments

Preliminary PFAR(s)? _____ Yes ☒ No _____ Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes ☒ No _____ Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-18
Forward Nose Ring and Aft Inlet Ring Phenolic (CCP) Section Condition

Motor No.: 360L029	Side: Left (A)	Date: 3/3/93
--------------------	----------------	--------------

Assessment Engineer(s)/Inspector(s): Jim FASSMAN, LARRY WILKS

Forward Nose and Aft Inlet Ring Phenolic Section Observations:

	Yes	No	Comment #
A. Cross-ply cracking in virgin material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
B. Ply lifting?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Record the Forward Nose Ring (-503) Char and Erosion Measurements Below:

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
28.0	<u>1.15</u>	<u>0.68</u>	<u>1.07</u>	<u>0.68</u>	<u>1.04</u>	<u>0.74</u>	<u>1.18</u>	<u>0.65</u>
30.0	<u>0.94</u>	<u>0.69</u>	<u>0.91</u>	<u>0.78</u>	<u>0.87</u>	<u>0.69</u>	<u>0.96</u>	<u>0.69</u>
32.0	<u>0.95</u>	<u>0.61</u>	<u>0.90</u>	<u>0.71</u>	<u>0.89</u>	<u>0.68</u>	<u>1.00</u>	<u>0.61</u>

Negative Margin of Safety? ☐ Yes ☒ No Station: _____ Degree: _____

Record the Aft Inlet Ring Char (-504) and Erosion Measurements Below:

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
34.0	<u>0.87</u>	<u>0.57</u>	<u>0.84</u>	<u>0.62</u>	<u>0.82</u>	<u>0.56</u>	<u>0.90</u>	<u>0.50</u>
36.0	<u>0.91</u>	<u>0.59</u>	<u>0.89</u>	<u>0.57</u>	<u>0.87</u>	<u>0.56</u>	<u>0.95</u>	<u>0.56</u>
38.0	<u>0.98</u>	<u>0.64</u>	<u>0.95</u>	<u>0.57</u>	<u>0.94</u>	<u>0.53</u>	<u>1.01</u>	<u>0.56</u>
39.0	<u>1.04</u>	<u>0.66</u>	<u>0.98</u>	<u>0.63</u>	<u>0.96</u>	<u>0.62</u>	<u>1.03</u>	<u>0.65</u>

Negative Margin of Safety? ☐ Yes ☒ No Station: _____ Degree: _____

Notes / Comments

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): _____

Clarification Form(s)? ☐ Yes ☒ No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-1
Nozzle Assembly Quick-look Condition

Motor No.: 360L029	Side: Right (B)	Date: 15 98																
Assessment Engineer(s)/Inspector(s): R. QUICK																		
<p>Nozzle Assembly Quick-look Observations:</p> <table style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:60%;"></th> <th style="width:10%; text-align: center;">Yes</th> <th style="width:10%; text-align: center;">No</th> <th style="width:20%; text-align: center;">Comment #</th> </tr> </thead> <tbody> <tr> <td>A. Metal Damage Due to Transportation or Handling?</td> <td style="text-align: center;">_____</td> <td style="text-align: center;">✓</td> <td style="text-align: center;">_____</td> </tr> <tr> <td>B. Phenolic Damage Due to Transportation or Handling?</td> <td style="text-align: center;">_____</td> <td style="text-align: center;">✓</td> <td style="text-align: center;">_____</td> </tr> <tr> <td>C. Foreign Material?</td> <td style="text-align: center;">_____</td> <td style="text-align: center;">✓</td> <td style="text-align: center;">_____</td> </tr> </tbody> </table>				Yes	No	Comment #	A. Metal Damage Due to Transportation or Handling?	_____	✓	_____	B. Phenolic Damage Due to Transportation or Handling?	_____	✓	_____	C. Foreign Material?	_____	✓	_____
	Yes	No	Comment #															
A. Metal Damage Due to Transportation or Handling?	_____	✓	_____															
B. Phenolic Damage Due to Transportation or Handling?	_____	✓	_____															
C. Foreign Material?	_____	✓	_____															
<p>Notes / Comments</p> <p>NOZZLE TOOK 2 INCHES OFF TOP OF NOZZLE CRACKS IN THE NOZZLE THE NOZZLE SURFACE WAS CRACKED AND SCRAP MARKED ON OD OF FIRED HSG FROM 240° - 305°</p>																		
<p>ORIGINAL PAGE IS OF POOR QUALITY</p>																		
<p>Preliminary PFAR(s)? _____ Yes _____ No ✓ Preliminary PFAR Number(s): _____</p>																		
<p>Clarification Form(s)? _____ Yes _____ No ✓ Clarification Form Page No.(s): _____</p>																		

POSTFLIGHT OBSERVATION RECORD (PFOR) C-2
Internal Nozzle Joint Condition

Motor No.: 360L029	Side: Right (B)	Date: 1, 23 85
Assessment Engineer(s)/Inspector(s): R. QUICK, T. FLESTON		
Joint: Nose Inlet-to-Flex Bearing-to-Cowl (Joint #2)		

Internal Nozzle Joint Observations:

	Yes	No	Comment #
A. Gas Penetration in the RTV (Terminated, Through)?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	3
B. RTV Not Below Char Line?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
C. RTV To the Primary O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
D. RTV Past the Primary O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
E. Uncured RTV?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
F. Voids Within RTV?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
G. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
H. Heat Affected or Eroded Virgin CCP, GCP/SCP, or adhesive?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
I. Damaged Phenolics?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
J. Bondline Edge Separations? Use Clarification Form.	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
K. Phenolics Axially Displaced From Housing?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
L. Heat Affected Metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
M. Unbonded or Blistered Paint?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
N. Corrosion?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	2
O. Excessive Grease in Threaded Bolt Holes?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
P. Bolt Hole Damage (Through, Threaded/Helical Coil Insert)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Q. Bent or Broken Bolts?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
R. Metal Damage (Joints or Housings)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments

Special Issue 3.3.2 - NO LDI'S DETECTED AT NOSE OF COWL INTERFERENCE
- HEAT AFFECTED RTV AT 318°, 63 FNBOARD OF FLOW SURFACES
- HEAT AFFECTED AL CLIP - BURNED HOLES IN RTV, HEAT AFFECTED COMPOSITE
- TERMINATED AT 913 ON OD CHAMFER OF COWL HSG.
- SEE CORN B-1 #2 ON PG B-51

3 - GAS PATH IN RTV AT 552° AND TERMINATED AT CHAMFER OF COWL
HSG (RTV & EPS BUILD UP)

ORIGINAL PAGE IS
OF POOR QUALITY

Preliminary PFAR(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Preliminary PFAR Number(s): _____
Clarification Form(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-3
Nose Inlet-to-Flex Bearing-to-Cowl Joint (Joint #2) Condition Drawing Worksheet


Motor No.: 360L029

Side: Right (B)

Date: 1/23/93

Assessment Engineer(s)/Inspector(s): R. QUICK, T. FRESTON

Sketch Observations Below (include locations and sizes of sketched features):



1. SCOT TO FORWARD G-RING
AT 250°
2. RTV FULL COVERAGE 360°
TYPICAL INTERMIXING OF
CLOTH AND PHENOLIC

(3) INTERMITTENT ^{Light} CORROSION 360°
(4) LIGHT CORROSION ON AFT EDGE
OF COWL HSG ID FLANGE
(5) INTERMITTENT SMALL AREA OF
MISSING PAINT (360°)

ification Form(s)? ☐ Yes ☒ No

Clarification Form Page No.(s):

ORIGINAL PAGE IS
OF POOR QUALITY

POSTFLIGHT OBSERVATION RECORD (PFOR) C-2
Internal Nozzle Joint Condition

Motor No.: 360L029	Side: Right (B)	Date: 1/28/93
Assessment Engineer(s)/Inspector(s): R. Quick T. FRESTON		
Joint: Nose Inlet-to-Throat (Joint #3)		
Internal Nozzle Joint Observations:		
	Yes	No
A. Gas Penetration in the RTV (Terminated, Through)?	_____	✓
B. RTV Not Below Char Line?	_____	✓
C. RTV To the Primary O-ring?	_____	✓
D. RTV Past the Primary O-ring?	_____	✓
E. Uncured RTV?	_____	✓
F. Voids Within RTV?	_____	✓
G. Grease Inhibiting RTV Backfill?	_____	✓
H. Foreign Material?	_____	✓
I. Heat Affected or Eroded Virgin CCP, GCP/SCP, or adhesive?	_____	✓
J. Damaged Phenolics?	_____	✓
K. Bondline Edge Separations? Use Clarification Form.	✓	✗
L. Phenolics Axially Displaced From Housing?	_____	✓
M. Heat Affected Metal?	_____	✓
N. Unbonded or Blistered Paint?	_____	✓
O. Corrosion?	_____	✓
P. Alignment Pin Damage?	_____	N/A
Q. Excessive Grease in Threaded Bolt Holes?	_____	✓
R. Bolt Hole Damage (Through, Threaded/Helical Coil Insert)?	_____	✓
S. Bent or Broken Bolts?	_____	✓
T. Metal Damage (Joints or Housings)?	_____	✓
Notes / Comments		

SEE Pg C-31A

Preliminary PFAR(s)? _____ Yes _____ No Preliminary PFAR Number(s): _____
 Clarification Form(s)? _____ Yes _____ No Clarification Form Page No.(s): C-31A

POSTFLIGHT OBSERVATION RECORD (PFOR) C-4
Nose Inlet-to-Throat Joint (Joint #3) Condition Drawing Worksheet

Motor No.: 360L029


Side: Right (B)

Date: 1/28/93

Assessment Engineer(s)/Inspector(s): R. QUICK T. FRESTON

Sketch Observations Below (include locations and sizes of sketched features):

LEN
2-17-93
~~1 - TYPICAL SCALLOPED IN BETWEEN BOLT HOLES.~~
~~SOOT TO PRIMARY O-RING 246-252~~
2 - GREASE COVERAGE IS NOMINAL



3 - NO EXCESS GREASE IN BOLT HOLES

5 - RTV BELOW CHAR LINE 360
6 - PLY SEPARATION FROM 290° - 300°
GAP = .010

4 - RTV REACHED NOSE INLET HOUSING 360° EXCEPT FOR
4-A LOC 295°-315° & 345°-355°

ification Form(s)? ☐ Yes ☒ No

Clarification Form Page No.(s):

POSTFLIGHT OBSERVATION RECORD (PFOR) C-2
Internal Nozzle Joint Condition

Motor No.: 360L029	Side: Right (B)	Date: 11-26-73																																																																																				
Assessment Engineer(s)/Inspector(s): R. D. J. C.																																																																																						
Joint: Throat-to-Forward Exit Cone (Joint #4)																																																																																						
<p>Internal Nozzle Joint Observations:</p> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:60%;"></th> <th style="width:10%;">Yes</th> <th style="width:10%;">No</th> <th style="width:20%;">Comment #</th> </tr> </thead> <tbody> <tr><td>A. Gas Penetration in the RTV (Terminated, Through)?</td><td></td><td><input checked="" type="checkbox"/></td><td></td></tr> <tr><td>B. RTV Not Below Char Line?</td><td></td><td><input checked="" type="checkbox"/></td><td></td></tr> <tr><td>C. RTV To the Primary O-ring?</td><td><input checked="" type="checkbox"/></td><td></td><td>SEE PG C-34</td></tr> <tr><td>D. RTV Past the Primary O-ring?</td><td></td><td><input checked="" type="checkbox"/></td><td></td></tr> <tr><td>E. Uncured RTV?</td><td></td><td><input checked="" type="checkbox"/></td><td></td></tr> <tr><td>F. Voids Within RTV?</td><td></td><td><input checked="" type="checkbox"/></td><td></td></tr> <tr><td>G. Grease Inhibiting RTV Backfill?</td><td></td><td><input checked="" type="checkbox"/></td><td></td></tr> <tr><td>H. Foreign Material?</td><td></td><td><input checked="" type="checkbox"/></td><td></td></tr> <tr><td>I. Heat Affected or Eroded Virgin CCP, GCP/SCP, or adhesive?</td><td></td><td><input checked="" type="checkbox"/></td><td></td></tr> <tr><td>J. Damaged Phenolics?</td><td></td><td><input checked="" type="checkbox"/></td><td></td></tr> <tr><td>K. Bondline Edge Separations? Use Clarification Form.</td><td><input checked="" type="checkbox"/></td><td></td><td>SEE PG C-34</td></tr> <tr><td>L. Phenolics Axially Displaced From Housing?</td><td></td><td><input checked="" type="checkbox"/></td><td></td></tr> <tr><td>M. Heat Affected Metal?</td><td></td><td><input checked="" type="checkbox"/></td><td></td></tr> <tr><td>N. Unbonded or Blistered Paint?</td><td></td><td><input checked="" type="checkbox"/></td><td></td></tr> <tr><td>O. Corrosion?</td><td><input checked="" type="checkbox"/></td><td></td><td>1, 2</td></tr> <tr><td>P. Alignment Pin Damage?</td><td></td><td><input checked="" type="checkbox"/></td><td></td></tr> <tr><td>Q. Excessive Grease in Threaded Bolt Holes?</td><td></td><td><input checked="" type="checkbox"/></td><td></td></tr> <tr><td>R. Bolt Hole Damage (Through, Threaded/Helical Coil Insert)?</td><td></td><td><input checked="" type="checkbox"/></td><td></td></tr> <tr><td>S. Bent or Broken Bolts?</td><td></td><td><input checked="" type="checkbox"/></td><td></td></tr> <tr><td>T. Metal Damage (Joints or Housings)?</td><td></td><td><input checked="" type="checkbox"/></td><td></td></tr> </tbody> </table>				Yes	No	Comment #	A. Gas Penetration in the RTV (Terminated, Through)?		<input checked="" type="checkbox"/>		B. RTV Not Below Char Line?		<input checked="" type="checkbox"/>		C. RTV To the Primary O-ring?	<input checked="" type="checkbox"/>		SEE PG C-34	D. RTV Past the Primary O-ring?		<input checked="" type="checkbox"/>		E. Uncured RTV?		<input checked="" type="checkbox"/>		F. Voids Within RTV?		<input checked="" type="checkbox"/>		G. Grease Inhibiting RTV Backfill?		<input checked="" type="checkbox"/>		H. Foreign Material?		<input checked="" type="checkbox"/>		I. Heat Affected or Eroded Virgin CCP, GCP/SCP, or adhesive?		<input checked="" type="checkbox"/>		J. Damaged Phenolics?		<input checked="" type="checkbox"/>		K. Bondline Edge Separations? Use Clarification Form.	<input checked="" type="checkbox"/>		SEE PG C-34	L. Phenolics Axially Displaced From Housing?		<input checked="" type="checkbox"/>		M. Heat Affected Metal?		<input checked="" type="checkbox"/>		N. Unbonded or Blistered Paint?		<input checked="" type="checkbox"/>		O. Corrosion?	<input checked="" type="checkbox"/>		1, 2	P. Alignment Pin Damage?		<input checked="" type="checkbox"/>		Q. Excessive Grease in Threaded Bolt Holes?		<input checked="" type="checkbox"/>		R. Bolt Hole Damage (Through, Threaded/Helical Coil Insert)?		<input checked="" type="checkbox"/>		S. Bent or Broken Bolts?		<input checked="" type="checkbox"/>		T. Metal Damage (Joints or Housings)?		<input checked="" type="checkbox"/>	
	Yes	No	Comment #																																																																																			
A. Gas Penetration in the RTV (Terminated, Through)?		<input checked="" type="checkbox"/>																																																																																				
B. RTV Not Below Char Line?		<input checked="" type="checkbox"/>																																																																																				
C. RTV To the Primary O-ring?	<input checked="" type="checkbox"/>		SEE PG C-34																																																																																			
D. RTV Past the Primary O-ring?		<input checked="" type="checkbox"/>																																																																																				
E. Uncured RTV?		<input checked="" type="checkbox"/>																																																																																				
F. Voids Within RTV?		<input checked="" type="checkbox"/>																																																																																				
G. Grease Inhibiting RTV Backfill?		<input checked="" type="checkbox"/>																																																																																				
H. Foreign Material?		<input checked="" type="checkbox"/>																																																																																				
I. Heat Affected or Eroded Virgin CCP, GCP/SCP, or adhesive?		<input checked="" type="checkbox"/>																																																																																				
J. Damaged Phenolics?		<input checked="" type="checkbox"/>																																																																																				
K. Bondline Edge Separations? Use Clarification Form.	<input checked="" type="checkbox"/>		SEE PG C-34																																																																																			
L. Phenolics Axially Displaced From Housing?		<input checked="" type="checkbox"/>																																																																																				
M. Heat Affected Metal?		<input checked="" type="checkbox"/>																																																																																				
N. Unbonded or Blistered Paint?		<input checked="" type="checkbox"/>																																																																																				
O. Corrosion?	<input checked="" type="checkbox"/>		1, 2																																																																																			
P. Alignment Pin Damage?		<input checked="" type="checkbox"/>																																																																																				
Q. Excessive Grease in Threaded Bolt Holes?		<input checked="" type="checkbox"/>																																																																																				
R. Bolt Hole Damage (Through, Threaded/Helical Coil Insert)?		<input checked="" type="checkbox"/>																																																																																				
S. Bent or Broken Bolts?		<input checked="" type="checkbox"/>																																																																																				
T. Metal Damage (Joints or Housings)?		<input checked="" type="checkbox"/>																																																																																				
<p>Notes / Comments</p> <p>1. LIGHT TO MODERATE CORROSION FROM 97°-107° AT SEAL REGION. CORROSION WAS INTERMITTENT IN THIS LOCATION.</p> <p>2. MODERATE TO HEAVY CORROSION ON AFT END OF THROAT HSG BETWEEN PRIMARY & SECONDARY O-RING SEAL SURFACE FROM 180-205 AND 85°-140°</p>																																																																																						
<p style="text-align: right;">ORIGINAL PAGE IS OF POOR QUALITY</p>																																																																																						

Preliminary PFAR(s)? ☐ Yes ☐ No Preliminary PFAR Number(s): _____

Clarification Form(s)? ☒ Yes ☐ No Clarification Form Page No.(s): C-33A

POSTFLIGHT OBSERVATION RECORD (PFOR) C-5
Throat-to-Forward Exit Cone Joint (Joint #4) Condition Drawing Worksheet

Motor No.: 360L029


Side: Right (B)

Date: 1/26/88

Assessment Engineer(s)/Inspector(s): R. QUICK

Sketch Observations Below (include locations and sizes of sketched features):

- ① RTV BELOW CHAR LINE FULL CIRCUMFERENCE
- ② RTV TO PRIMARY O-RING FROM 252.5°-345° & 355°-120°
- ③ SEPARATIONS ADHESIVE TO METAL, GCP TO CCP & WITHIN GCP



④ NO EXCESS GREASE IN HOLES
⑤ MINIMAL GREASE COVERAGE ON FLANGES

⑥ PHENOLIC DISCOLORED LOOKS RUSTY FROM 45 TO 188°

ORIGINAL PAGE IS
OF POOR QUALITY

Clarification Form(s)? ☐ Yes ☐ No

Clarification Form Page No.(s):

POSTFLIGHT OBSERVATION RECORD (PFOR) C-2
Internal Nozzle Joint Condition

Motor No.: 360L029 Side: Right (B) Date: 27 JAN 1993

Assessment Engineer(s)/Inspector(s): JIM PASSMAN, TREVOR FRESTON

Joint: Aft End Ring-to-Fixed Housing (Joint #5)

Internal Nozzle Joint Observations:

	Yes	No	Comment #
A. Gas Penetration in the RTV (Terminated, Through)?		✓	
B. RTV Not Below Char Line?		✓	
C. RTV To the Primary O-ring?	✓		①
D. RTV Past the Primary O-ring?		✓	
E. Uncured RTV?		✓	
F. Voids Within RTV?	✓		②
G. Foreign Material?		✓	
H. Heat Affected or Eroded Virgin CCP, GCP/SCP, or adhesive?		✓	
I. Damaged Phenolics?		✓	
J. Bondline Edge Separations? Use Clarification Form.		✓	
K. Phenolics Axially Displaced From Housing?		✓	
L. Heat Affected Metal?		✓	
M. Unbonded or Blistered Paint?		✓	
N. Corrosion?	✓		③
O. Alignment Pin Damage?		✓	
P. Excessive Grease in Threaded Bolt Holes?		✓	
Q. Bolt Hole Damage (Through, Threaded/Helical Coil Insert)?		✓	
R. Bent or Broken Bolts?		✓	
S. Metal Damage (Joints or Housings)?		✓	

Notes / Comments

- ① RTV TO PRIMARY O-RING AT 40°-70°, 130°, AND 220°-250°.
- ② LARGE VOID IN RTV COVERING AFT MOST END APPROX 0.5" WIDE x 10.3" CIRC FROM 140°-157°. LARGE VOID IN RTV (SAME LOCATION) FROM 165°-187°, 0.5" MAX WIDTH x 14.3" CIRC. SMALL VOIDS (0.2" x 0.3" TYP) INTERMITTENT 360°.
- ③ CORROSION AS NOTED ON PFOR C-6 (PAGE C-36).

Preliminary PFAR(s)? Yes ☒ No

Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes ☒ No


Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-6
Aft End Ring-to-Fixed Housing Joint (Joint #5) Condition Drawing Worksheet

Motor No.: 360L029	Side: Right (B)	Date: 27 JAN 1993
Assessment Engineer(s)/Inspector(s): <u>JIM PASSMAN, TREVOR FRESTON</u>		

Sketch Observations Below (include locations and sizes of sketched features):

- ① MEDIUM CORROSION INTERMITTENT ~~360°~~ FROM 150°-0°-80°.
- ② NOMINAL GREASE COVERAGE. WATER IN NOTED AREA, APPEARS TO BE FROM DISASSEMBLY. LIGHT CORROSION ALSO FOUND IN NOTED AREA INTERMITTENT 360°.
- ③ RTV REACHED PRIMARY O-RING AT 40°-70°, 130°, AND 220°-250°



Clarification Form(s)? ☐ Yes ☒ No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-7
Cowl Insulation Segment Condition

Motor No.: 360L029	Side: Left (A) Right (B)	Date: 27/Jun/93
Assessment Engineer(s)/Inspector(s): PETE MILLER, L. WILKES		

Cowl Insulation Segment Observations:

	Yes	No	Comment #
A. Spring Pin Holes Completely Through the Cowl Segment?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
B. Abnormal Heat Effects or Erosion?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
C. Soot Between the Cowl Segment and Cowl Housing?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
D. Bondline Failure Mode? Data Collection Only.	N/A	N/A	1

Notes / Comments	<u>Adhesive Metal</u>	<u>Adhesive Segment</u>	<u>Cohesive Segment</u>
1) 0-45	20%	60%	20%
45-90	15%	55%	30%
90-135	50%	35%	15%
135-180	50%	30%	20%
180-225	50%	35%	15%
225-270	15%	70%	15%
270-315	50%	30%	20%
315-360	30%	50%	20%

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): _____

Clarification Form(s)? ☐ Yes ☒ No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-8
Flexible Bearing, Flexible Bearing Protector, and Flexible Boot Condition

Motor No.: 360L029	Side: Right (B)	Date: 27 JAN 1993
Assessment Engineer(s)/Inspector(s): Jim PASSMAN, TREVOR FRESTON, WILKES		

Flexible Bearing, Bearing Protector, and Boot Observations:

	Yes	No	Comment #
A. Bearing Protector Burn-Through?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
B. Cracks Through the Bearing Protector?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
C. Bearing Protector Heat Effects or Erosion Other Than at Cowl Vent Hole Locations?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
D. Soot Between the Bearing Protector and Flexible Bearing?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
E. Heat Effects to the Flexible Bearing?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
F. Bent or Broken Bearing Protector Bolts?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
G. Flexible Boot Burn-Through?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
H. Abnormal Heat Effects or Erosion to Flexible Boot ID?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
I. Foreign Material in Boot Cavity?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments

Special Issue 3.3.1 NO ABNORMAL EROSION OR OTHER CONDITIONS WERE OBSERVED ON THE BEARING PROTECTOR OD OR ON THE FLEX BOOT ID AROUND FULL CIRCUMFERENCE.

ORIGINAL PAGE IS
OF POOR QUALITY

Preliminary PFAR(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Preliminary PFAR Number(s): _____
Clarification Form(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Clarification Form Page No. (s): _____

Thiokol CORPORATION

SPACE OPERATIONS

POSTFLIGHT OBSERVATION RECORD (PFOR) C-9
Flexible Bearing Protector Thickness Measurements

Motor No.: 360L029

Side: Right (B)


Date: 2-1-93

Assessment Engineer(s)/Inspector(s): R. HASTELSON, M. ENRIQUETE SR

Record the Flexible Bearing Protector Gas Impingement Area Thickness Measurements (see figure) Below:

Degree Location	Thickness Measurement "A" (inches)	Degree Location	Thickness Measurement "A" (inches)	Degree Location	Thickness Measurement "A" (inches)
0	.719	120	.685	240	.702
10	.712	130	.695	250	.670
20	.726	140	.688	260	.686
30	.735	150	.663	270	.662
40	.712	160	.696	280	.709
50	.725	170	.716	290	.722
60	.712	180	.716	300	.720
70	.704	190	.710	310	.698
80	.696	200	.715	320	.706
90	.703	210	.705	330	.714
100	.693	220	.713	340	.703
110	.698	230	.706	350	.725

700

17745
TW42 42 93
ENTERED IN
EPA

* "A" is the minimum thickness of the bearing protector in-line with the cowl vent holes. It corresponds to the deepest gas impingement location.

Notes / Comments

ORIGINAL PAGE IS
OF POOR QUALITY

Preliminary PFAR(s)? ☐ Yes ☒ No

Preliminary PFAR Number(s): _____

Clarification Form(s)? ☐ Yes ☒ No

Clarification Form Page No.(s): _____

REVISION _____

DOC NO. TWR-64222
SEC _____

VOL _____

PAGE C-39

POSTFLIGHT OBSERVATION RECORD (PFOR) C-10
Throat Diameter Measurements (Data Collection Only)

Motor No.: 360L029	Side: Right (B)	Date: 01-28-93
--------------------	-----------------	----------------

Assessment Engineer(s)/Inspector(s): R.R. Gallegos, Jed BENSON

Record the Nozzle Throat Diameter Measurements Below:

Degree Location	Diameter Measurement (inches)
0	<u>55.983"</u>
45	<u>55.990"</u>
90	<u>55.987"</u>
135	<u>55.960</u>

Notes / Comments

SL-45062

Clarification Form(s)? ☐ Yes ☒ No

Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-11
Outer Boot Ring Char and Erosion Measurements and Flexible Boot Condition

Motor No.: 360L029	Side: Right (B)	Date: 3/3/93
Assessment Engineer(s)/Inspector(s): Jim Passman, Mark Clark		

Flexible Boot/Outer Boot Ring Separation Observations:

A. Heat Effects in Boot/OBR Separation?

Yes _____ No ☒ Comment # _____

Record the Outer Boot Ring Char and Erosion Measurements Below:

Station Location	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
8.0	—	0.93*	—	1.04*	—	1.01*	—	0.91*
9.0	0.08	0.85	0.06	0.87	0.09	0.84	0.04	0.84
10.0	0.11	0.87	0.05	0.88	0.08	0.82	0.03	0.86
11.3	0.18	0.81	0.07	0.98	0.06	0.90	0.09	0.87

Negative Margin of Safety? _____ Yes ☒ No Station: _____ Degree: _____

Record the Number of Piles Remaining on the Flexible Boot:

Degree Location	Piles Remaining
0	3.4
90	3.9
180	4.0
270	3.3

Negative Margin of Safety? _____ Yes ☒ No Degree: _____

Notes / Comments

* TOTAL (CHAR AND EROSION)

Preliminary PFAR(s)? _____ Yes ☒ No Preliminary PFAR Number(s): _____

Clarification Form(s)? _____ Yes ☒ No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360L029	Side: Right (B)	Date: 5 FEB 1993
Assessment Engineer(s)/Inspector(s): Jim Passman, Pete Miller		
Phenolic Subassembly: Aft Exit Cone Assembly		

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	0°-45°	45°-90°	90°-135°	135°-180°	180°-225°	225°-270°	270°-315°	315°-0°
Metal-to-Adhesive	—	5%	5%	50%	50%	25%	5%	5%
Within Adhesive								
Adhesive-to-GCP				20%	20%	30%	10%	5%
Within GCP	100%	95%	95%	30%	30%	45%	85%	90%
GCP-to-CCP								
Within CCP								

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
	0°-45°	45°-90°	90°-135°	135°-180°	180°-225°	225°-270°	270°-315°	315°-0°
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP	100%	100%	100%	100%	100%	100%	100%	100%

Phenolic Removal Method: WEDGE, HAND PEEL. VERY DIFFICULT, COULDN'T REMOVE ALL

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?		✓	
B. Voids in Adhesive?	✓		(1)
C. Corrosion?	✓		(2)
D. Foreign Material?		✓	
E. Voids in Polysulfide (Aft Exit Cone Polysulfide Groove)?	✓		(3)

Notes / Comments

- (1) ONE VOID NOTED AT 244°, LOCATED 20.2" FROM FWD END, MEASURING 0.60" AXIAL x 0.40" CIRC.
 (2) MEDIUM CORROSION IN ADHESIVE/METAL FAILURE AREAS FROM 135°-270°.
 (3) SMALL VOIDS LOCATED INTERMITTENTLY FULL CIRC. POLYSULFIDE DID NOT FULLY FILL GROOVE IN SEVERAL LOCATIONS.

Primary PFAR(s)? Yes ✓ No

Preliminary PFAR Number(s):

Clarification Form(s)? ✓ Yes ✓ No
 S.P.

Clarification Form Page No.(s): C-42A

General Hardware Clarification Form

Motor No.: 360L029


Side: ☐ Left (A) ☒ Right (B)

Date: 10 FEB 1993

Assessment Engineer(s)/Inspector(s): JIM PASSMAN

Description: AFT EXIT CONE POLYSULFIDE GROOVE FILL

Sketch Observations Below (include locations and sizes of sketched features):



Corresponding Comment Number(s): (3)

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360L029	Side: Right (B)	Date: 1-29-93
--------------------	-----------------	---------------

Assessment Engineer(s)/Inspector(s): WILKES/FRESTON/LANGE/SUNYDIE/M...T.

Phenolic Subassembly: Forward Exit Cone Assembly

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

SEE NOTE 1

	Degree Location						
	0-90	90-180	180-270	270-360			
Metal-to-Adhesive	25	30	25	20			25
Within Adhesive	10	10	10	10			10
Adhesive-to-GCP	65	60	65	70			65
Within GCP							
GCP-to-CCP							
Within CCP							

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

N.A.

	Degree Location						
	0-90	90-180	180-270	270-360			
Metal-to-Adhesive							
Within Adhesive							
Adhesive-to-GCP							

Phenolic Removal Method: _____

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	2
C. Corrosion?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	3
D. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments ① SEE CLARIFICATION FORM PAGE C-43A FOR DEVIATIONS FROM NORMAL PHENOLIC REMOVAL PROCEDURES.

② SEE PFOR CLARIFICATION FORM PAGE C-43B.

③ TYPICAL MED-TO-HEAVY CORROSION INTERMITTENTLY AROUND 95% OF THE CIRCUMFERENCE OVER AFT 4-TO-8 INCHES AND AROUND 30% OF CIRCUMFERENCE OVER FWD 2-TO-6 INCHES. NO CORROSION ON EXPOSED MID-SECTION METAL SURFACE.

Primary PFAR(s)? ☒ Yes ☒ No Preliminary PFAR Number(s): _____

Clarification Form(s)? ☒ Yes ☐ No Clarification Form Page No.(s): C-43A & B

General Hardware Clarification Form

Motor No.: 360L029	Side: <input type="checkbox"/> Left (A) <input checked="" type="checkbox"/> Right (B)	Date: 1-29-93
Assessment Engineer(s)/Inspector(s): WILKES/FRESTON/LANGE/SIMMONS		
Description: PHENOLIC BONDLINE CONDITION, FWD EXIT CONE ASSEMBLY.		
<p>Sketch Observations Below (include locations and sizes of sketched features):</p> <p>SEE CLARIFICATION FORM PAGE C-16A FOR NORMAL PROCEDURE OF PHENOLIC LINED REMOVAL.</p> <p>THE ASAM-29B NOZZLE FWD EXIT CONE HAD 4.0 TO 8.0 INCHES OF CONE LINER REMAINING ON AFT END, AROUND FULL CIRCUMFERENCE AND 4.0 TO 10 INCHES WIDE AXIALLY FROM 30° TO 340°. THE REMAINING MIDDLE SECTION SHOWED CCP/GCP SEPARATIONS. AN AXIAL SAW CUT WAS ^{made} THROUGH THE CCP TO THE GCP INTERFACE. THREE WEDGES WERE DRIVEN BETWEEN THE GCP AND CCP. THE AFT CCP ELEMENT SEPARATED AT GCP/CCP INTERFACE. THE FWD CCP ELEMENT SEPARATED AT GCP/CCP INTERFACE EXCEPT FOR A ONE INCH WIDE, AXIAL, BAND AROUND CIRCUMFERENCE WAS WITH GCP SEPARATION. THIS BAND WAS LOCATED ONE INCH FROM FWD GCP SURFACE.</p>		

ORIGINAL PAGE IS
OF POOR QUALITY

Corresponding Comment Number(s): 1

Corresponding Comment Number(s): 2

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360L029 Side: Right (B) Date: 29 JAN 1993

Assessment Engineer(s)/Inspector(s): Jim PASSMAN, TREUOR FRESTON

Phenolic Subassembly: Throat Assembly

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location								total
	45°-135°	135°-225°	225°-315°	315°-45°					
Metal-to-Adhesive	75	100	100	100					94
Within Adhesive									
Adhesive-to-GCP	20								5
Within GCP	5								1
GCP-to-CCP									
Within CCP									

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location								
	45°-135°	135°-225°	225°-315°	315°-45°					
Metal-to-Adhesive									
Within Adhesive									
Adhesive-to-GCP									

Phenolic Removal Method: _____

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?		✓	
B. Voids in Adhesive?	✓		(1)
C. Corrosion?	✓		
D. Foreign Material?		✓	

Notes / Comments

- (1) WORMHOLE VOIDS ON AFT 8.5" OF 45°-135° SECTION. MAX CONDITION MEASURES 6.5" AXIAL BY 2.5" CIRC.. A FEW SMALL VOIDS (0.40" MAX DIA) TYPICALLY AT 0.10" TO 0.25" DIA WERE FOUND SCATTERED AROUND THE CIRCUMFERENCE.
- (2) CORROSION - MEDIUM TO HEAVY FOUND ON ALL AREAS OF METAL TO ADHESIVE FAILURE.

Preliminary PFAR(s)? Yes ☒ No ☒

Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes ☒ No ☒

Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360L029	Side: Right (B)	Date: 2/1/93
Assessment Engineer(s)/Inspector(s): R. QUICK T. FRESTON		
Phenolic Subassembly: Aft Inlet/Forward Nose Rings		

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location								
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0	
Metal-to-Adhesive	100%	100%	100%	100%	100%	100%	60%	100%	95
Within Adhesive									
Adhesive-to-GCP							40%		5
Within GCP									
GCP-to-CCP									
Within CCP									

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								

Phenolic Removal Method: _____

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?		<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input checked="" type="checkbox"/>		SEE SPECIAL ISSUES
C. Corrosion?	<input checked="" type="checkbox"/>		1
D. Foreign Material?		<input checked="" type="checkbox"/>	

Notes / Comments 1- MEDIUM CORROSION 340°

296° NO LDI INDICATION

Special Issue 3.3.7 144° AT 148° AXIAL .32, CIRCUM. .42 (LDI)

Special Issue 3.3.11 90° DEPTH .02 AXIAL .33 CIRCUM. 25 (LDI)

335° DEPTH .02 AXIAL .70 CIRCUM. 40 (LDI)

Primary PFAR(s)? Yes ☒ No ☐ Preliminary PFAR Number(s): _____

Clarification Form(s)? Yes ☒ No ☐ Clarification Form Page No.(s): _____

CRITICAL FAILURE
OF POOR QUALITY

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360L029	Side: Right (B)	Date: 4/2/93
Assessment Engineer(s)/Inspector(s): R. QUICK T. FRESTON		
Phenolic Subassembly: Nose Cap		

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								
Within GCP								
GCP-to-CCP	100%	100%	100%	100%	100%	100%	100%	100%
Within CCP								

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0
Metal-to-Adhesive	20%	20%	20%	20%	20%	20%	20%	20%
Within Adhesive								
Adhesive-to-GCP	80	80	80	80	80	80	80	80

Phenolic Removal Method: _____

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?		<input checked="" type="checkbox"/>	
B. Voids in Adhesive?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	SEE SPECIAL ISSUES
C. Corrosion?	<input checked="" type="checkbox"/>		1
D. Foreign Material?		<input checked="" type="checkbox"/>	

Notes / Comments: 1-LIGHT CORROSION AFT 3.0 IN & FWD 1.5-2.0 IN. FULL CIRCUM
177° NO INDICATION
Special Issue 3.3.4 90° DEPTH .02, AXIAL = .32, CIRCUM = .25, 335° DP .02, AXIAL = .75, CIRCUM = .40 (LD)
191° DEPTH .03 AXIAL = .20, CIRCUM = .23 (LDI)
Special Issue 3.3.5 121° NO INDICATION
210° NO INDICATION
Special Issue 3.3.11 SEE PG C-45

Primary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): _____

Clarification Form(s)? ☐ Yes ☒ No Clarification Form Page No. (s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360L029	Side: Right (B)	Date: 1-28-93
Assessment Engineer(s)/Inspector(s): WILKES / TELLEPS		
Phenolic Subassembly: Cowl Assembly		
Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):		
	Degree Location	
	0-360	
Metal-to-Adhesive	100	
Within Adhesive		
Adhesive-to-SCP		
Within SCP		
SCP-to-CCP		
Within CCP		
Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):		
	Degree Location	
	1A	
Metal-to-Adhesive		
Within Adhesive		
Adhesive-to-SCP		
Phenolic Removal Method: _____		
<u>Metal Housing Bondline Surface Observations:</u>		
	Yes	No
A. Soot?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
B. Voids in Adhesive?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
C. Corrosion?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
D. Foreign Material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Notes / Comments ① SEE PFOR CLARIFICATION FORM PAGES C-47A, E, C. ② SEE NOTES ON CLARIFICATION FORM PAGE C-47D. Special Issue 3.3.8 - SEE CLARIFICATION FORM PAGE C-47A NOTE 2. Special Issue 3.3.11 - SEE CLARIFICATION FORM PAGE C-47C NOTES 1 & 2.		
Preliminary PFAR(s)?	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
Preliminary PFAR Number(s): _____		
Clarification Form(s)?	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
Clarification Form Page No.(s): C-47A, B, C & D		

Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: 360L029 Side: ☐ Left (A) ☒ Right (B) Date: 1-28-93

Assessment Engineer(s)/Inspector(s): WILKES / TELLERS

Nozzle Subassembly: COWL

Record Bondline Adhesive Void Measurements and Locations Below:

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd FROM CHAN CORNER	Distance From Aft
44	.30	.05	0.50	
44	.30	.10	0.60	
47	.35	.20	0.50	
47	.45	.20	2.40	
47	.40	.10	2.95	
49	.10	.45	2.70	
50	.15	.65	0.30	
50	.70	.05	1.75	
51	.10	.30	1.80	
52	.20	.30	2.00	
52	.35	.10	1.70	
55	.90	.10	0.90	
57	.30	.10	0.10	

Notes / Comments ① MANY SMALL ADHESIVE VOIDS, 0.25 IN. DIA. MAX, WERE OBSERVED FROM 44° TO 80°. VERY FEW VOIDS WERE OBSERVED AROUND REMAINING CIRCUMFERENCE.
② NO ADHESIVE VOIDS WERE OBSERVED AT 7° AND 9°. HOWEVER ADHESIVE FILLED METAL SURFACE PIT REPAIR AREAS WERE OBSERVED AT 8° AND 10° WHICH ALMOST CORRELATES TO NOTER LDI SIZES. IT SHOULD BE NOTED THAT A REPAIR AREA ON THE HOUSING AT 0° HAS NO RESPECTIVE LDI LISTED.

Corresponding Comment Number(s): 1, 3

Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: 360L029	Side: <input type="checkbox"/> Left (A) <input checked="" type="checkbox"/> Right (B)	Date: 1-28-93
Assessment Engineer(s)/Inspector(s): WILKES / TELLER'S		
Nozzle Subassembly: COWL		

Record Bondline Adhesive Void Measurements and Locations Below:

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd FROM CHAM CORNER	Distance From Aft
57	.40	.10	0.50	
58.5	.10	.30	0.85	
58.5	.10	.30	1.55	
61	.90	.15	0.30	
51-63	.70	3.80	0.00	
59.5	.35	.05	1.85	
61	.40	.15	0.70	
63	.55	.10	1.70	
64	.70	.10	1.00	
66	.35	.05	1.95	
67	.40	.10	0.90	
69.5	.40	.10	0.90	
70	.35	.10	0.30	

Notes / Comments

① A LIGHT GREEN STAIN WAS OBSERVED IN THE ADHESIVE
AFT FROM SPRING PIN AT 130° TO AFT END OF NOZZLE
AND MEASURED 1.50 IN. CIRCUMFERENCE. THERE WAS NO
EVIDENCE OF THIS STAIN AT CORRESPONDING LOCATION ON METAL
HOUSING.

ORIGINAL PAGE IS
OF POOR QUALITY

Corresponding Comment Number(s): 1

Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: 360L029	Side: <input type="checkbox"/> Left (A) <input checked="" type="checkbox"/> Right (B)	Date: 1-28-93
Assessment Engineer(s)/Inspector(s): WILKES / TELLERS		
Nozzle Subassembly: COWL		

Record Bondline Adhesive Void Measurements and Locations Below:

SURFACE METAL HOUSING PIT REPAIRS.

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd FROM CHAM CORNER	Distance From Aft
79.5	.50	.10	0.10	
76	.30	.10	0.00	
225	.30	.05	3.60	
276	.30	.15	0.20	
* 0	.40	.50	0.50	
* 8	.30	.30	0.30	
* 10	.40	.40	0.50	
* 261	.20	.50	ON CHAM SURFACE	
* 272	.25	.45	ON CHAM SURFACE	

* METAL HOUSING BONDLINE SURFACE PIT REPAIR AREAS

Notes / Comments ① SEE PFCR CLARIFICATION FORMS PAGES C-47A, B & C FOR ADHESIVE VOIDS.

② FIVE METAL HOUSING PIT REPAIR AREAS WERE LOCATED AS DESCRIBED IN LAST ITEMS IN ABOVE CHART. PHOTOS WERE NOT TAKEN BECAUSE REPAIR AREAS WERE TOO SHALLOW TO APPEAR IN PHOTOS.

ORIGINAL PAGE IS
OF POOR QUALITY

Corresponding Comment Number(s): 1, 4

Record Bondline ~~Adhesive Void~~ Measurements and Locations Below:

ORIGINAL PAGE IS
OF POOR QUALITY

POSTFLIGHT OBSERVATION RECORD (PFOR) C-12
Nozzle Subassembly Phenolic Bondline Condition

Motor No.: 360L029	Side: Right (B)	Date: 3/FEB/93
Assessment Engineer(s)/Inspector(s): Jim Passman, Pete Miller		
Phenolic Subassembly: Fixed Housing Assembly		

Record Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location								
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-360	Total
Metal-to-Adhesive	15	3	5	5	10	15	15	10	10
Within Adhesive									
Adhesive-to-GCP									
Within GCP	85	97	95	95	90	10	15	90	72
GCP-to-CCP						75	70		18
Within CCP									

Record Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-360
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP	100	100	100	100	100	100	100	100

Phenolic Removal Method: _____

Metal Housing Bondline Surface Observations:

	Yes	No	Comment #
A. Soot?		✓	
B. Voids in Adhesive?	✓		1
C. Corrosion?		✓	
D. Foreign Material?		✓	

Notes / Comments

1) see Clarification Form

Preliminary PFAR(s)? _____ Yes _____ ☒ No Preliminary PFAR Number(s): _____

Clarification Form(s)? ☒ Yes _____ No Clarification Form Page No.(s): C-48A

POSTFLIGHT OBSERVATION RECORD (PFOR) C-13
Cowl Ring Phenolic (CCP) Section Condition

Motor No.: 360L029	Side: Right (B)	Date: 6-10-93
--------------------	-----------------	---------------

Assessment Engineer(s)/Inspector(s): M. Clark

Cowl Phenolic Section Observations:

	Yes	No	Comment #
A. Cross-ply cracking in virgin material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
B. Ply lifting?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Record the Cowl Char and Erosion Measurements Below:

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
0.3	.27	.52	.23	.57	.24	.54	.27	.54
1.0	.34	.51	.26	.62	.30	.53	.27	.56
2.0	.31	.61	.31	.54	.34	.50	.33	.60
3.0	.37	.61	.30	.54	.37	.47	.34	.57
4.0	.37	.59	.34	.58	.35	.50	.29	.68
5.0	.37	.59	NA	NA	NA	NA	NA	NA
6.0	—	0.99*	—	0.98*	—	0.92*	—	1.05*
6.8	—	0.69*	—	0.99*	—	0.99*	NA	NA

Negative Margin of Safety? ☐ Yes ☒ No Station: _____ Degree: _____

Notes / Comments * TOTAL (CHAR AND EROSION)

Special Issue 3.3.9

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): _____

Clarification Form(s)? ☐ Yes ☒ No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-14
Forward Exit Cone Phenolic (CCP) Section Condition

Motor No.: 360L029 Side: Right (B) Date: 6-10-93

Assessment Engineer(s)/Inspector(s): M. Clark

Forward Exit Cone Phenolic Section Observations:

	Yes	No	Comment #
A. Cross-ply cracking in virgin material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
B. Ply lifting?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Record the Forward Exit Cone Char and Erosion Measurements Below:

Station Location	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
1.0	NA	NA	.37	.71	.39	.67	.41	.67
4.0			.33	.69	.35	.72	.36	.70
4.6			.32	.70	.34	.74	.35	.71
8.0			.31	.74	.34	.68	.34	.67
12.0			NA	NA	NA	NA	NA	NA
16.0								
20.0								
24.0								
28.0					NA	NA	NA	NA
32.0					.15	.71	.19	.68
32.9					.19	.66	.19	.62
34.0	NA	NA	NA	NA	.19	.69	.19	.65

Negative Margin of Safety? ☐ Yes ☒ No Station: Degree:

Notes / Comments

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s):
 Clarification Form(s)? ☒ Yes ☐ No Clarification Form Page No.(s): C-50A

POSTFLIGHT OBSERVATION RECORD (PFOR) C-19
Forward Exit Cone Phenolic (CCP) Section Condition

Motor No.: 360L029	Side: Right (B)	Date: 4-8-93
--------------------	-----------------	--------------

Assessment Engineer(s)/Inspector(s): L.E. WILKES

AFT Exit Cone Phenolic Section Observations:

- A. Cross-ply cracking in virgin material?
B. Ply lifting?

Yes	No	Comment #
<input type="checkbox"/>	<input checked="" type="checkbox"/>	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Record the Forward Exit Cone Char and Erosion Measurements Below:

Station Location	180°		190°		200°		210°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
118.77	NA	NA	.150	.640	.140	.520	NA	NA
113.77	.150	.600	.190	.570	.170	.570	.180	.600
107.77	.150	.580	.150	.560	.160	.510	.160	.570
101.77	.130	.510	.130	.560	.130	.570	.140	.560
95.77	NA	NA	.120	.550	.120	.600	.110	.570
89.77	↓	↓	NA	NA	.110	.560	NA	NA
83.77	↓	↓	↓	↓	NA	NA	↓	↓
77.77	↓	↓	↓	↓	↓	↓	↓	↓
73.77	↓	↓	↓	↓	↓	↓	↓	↓

Negative Margin of Safety? ☐ Yes ☒ No Station: _____ Degree: _____

Notes / Comments

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): _____
 Clarification Form(s)? ☐ Yes ☒ No Clarification Form Page No.(s): _____

**ORIGINAL PAGE IS
OF POOR QUALITY**

POSTFLIGHT OBSERVATION RECORD (PFOR) C-15
Fixed Housing Phenolic (CCP) Section Condition

Motor No.: 360L029	Side: Right (B)	Date: 6-10-93
Assessment Engineer(s)/Inspector(s): M. Clark		

Fixed Housing Phenolic Section Observations:

- A. Cross-ply cracking in virgin material?
B. Ply lifting?

Yes	No	Comment #
<u> </u>	<u>✓</u>	<u> </u>
<u> </u>	<u>✓</u>	<u> </u>

Record the Fixed Housing Char and Erosion Measurements Below:

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
0.0	<u>.15</u>	<u>1.15</u>	<u>.08</u>	<u>1.16</u>	<u>.10</u>	<u>.95</u>	<u>0</u>	<u>1.31</u>
1.0	<u>.06</u>	<u>.96</u>	<u>.04</u>	<u>.89</u>	<u>.10</u>	<u>.94</u>	<u>.04</u>	<u>.37</u>
2.0	<u>0</u>	<u>.95</u>	<u>0</u>	<u>.92</u>	<u>0</u>	<u>.96</u>	<u>0</u>	<u>.73</u>
3.0	<u>0</u>	<u>.73</u>	<u>0</u>	<u>.89</u>	<u>0</u>	<u>.96</u>	<u>0</u>	<u>.91</u>
4.0	<u>0</u>	<u>.83</u>	<u>0</u>	<u>.91</u>	<u>0</u>	<u>.95</u>	<u>0</u>	<u>.90</u>
5.0	<u>0</u>	<u>.81</u>	<u>0</u>	<u>.97</u>	<u>0</u>	<u>.93</u>	<u>0</u>	<u>.83</u>
6.0	<u>0</u>	<u>.94</u>	<u>0</u>	<u>.92</u>	<u>0</u>	<u>.97</u>	<u>0</u>	<u>.85</u>
7.0	<u>0</u>	<u>.97</u>	<u>0</u>	<u>.89</u>	<u>0</u>	<u>.91</u>	<u>0</u>	<u>.77</u>
8.0	<u>0</u>	<u>.71</u>	<u>0</u>	<u>.61</u>	<u>0</u>	<u>.91</u>	<u>0</u>	<u>.76</u>
9.0	<u>.12</u>	<u>.52</u>	<u>.17</u>	<u>.54</u>	<u>.06</u>	<u>.74</u>	<u>.12</u>	<u>.74</u>
10.75	<u>.18</u>	<u>1.45</u>	<u>.17</u>	<u>.76</u>	<u>.24</u>	<u>1.37</u>	<u>.18</u>	<u>.76</u>

Negative Margin of Safety? Yes ✓ No Station: Degree:

Notes / Comments

Preliminary PFAR(s)? Yes ✓ No Preliminary PFAR Number(s):
Clarification Form(s)? Yes ✓ No Clarification Form Page No.(s):

ORIGINAL PAGE IS
OF POOR QUALITY

POSTFLIGHT OBSERVATION RECORD (PFOR) C-16
Throat Inlet Assembly Phenolic (CCP) Section Condition

Motor No.: 360L029 Side: Right (B) Date: 3/3/13

Assessment Engineer(s)/Inspector(s): JIM PASSMAN, CAROL WILKES

Throat Inlet Assembly Phenolic Section Observations:

- A. Cross-ply cracking in virgin material?
B. Ply lifting?

Yes	No	Comment #
<input type="checkbox"/>	<input checked="" type="checkbox"/>	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Record the Throat Inlet Ring and Throat Ring Char and Erosion Measurements Below:

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
1.0	1.06	0.65	1.06	0.72	1.10	0.57	1.06	0.53
2.0	1.09	0.67	1.07	0.75	1.12	0.57	1.13	0.51
4.0	1.13	0.68	1.14	0.67	1.16	0.64	1.17	0.64
6.0	1.17	0.66	1.18	0.69	1.19	0.64	1.21	0.64
8.0	1.19	0.58	1.19	0.62	1.19	0.56	1.23	0.55
10.0	1.19	0.60	1.19	0.61	1.18	0.53	1.21	0.50
12.0	1.15	0.56	1.16	0.62	1.16	0.53	1.18	0.57
14.0	1.14	0.55	1.13	0.65	1.15	0.53	1.15	0.59
16.0	1.09	0.55	1.08	0.68	0.99	0.69	1.00	0.68
18.0	0.99	0.56	0.97	0.66	0.98	0.63	0.96	0.64
20.0	0.81	0.61	0.84	0.59	0.81	0.67	0.78	0.66
22.0	0.56	0.67	0.54	0.70	0.53	0.70	0.56	0.63
23.0	0.45	0.75	0.46	0.74	0.46	0.70	0.42	0.68

Negative Margin of Safety? ☐ Yes ☒ No Station: _____ Degree: _____

Notes / Comments

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): _____

Clarification Form(s)? ☐ Yes ☒ No Clarification Form Page No.(s): _____

POSTFLIGHT OBSERVATION RECORD (PFOR) C-17

Nose Cap Phenolic (CCP) Section Condition

Motor No.: 360L029	Side: Right (B)	Date: 3/3/93
--------------------	-----------------	--------------

Assessment Engineer(s)/Inspector(s): Jim. Passman, Larry Wilkes

Nose Cap Phenolic Section Observations:

Yes	No	Comment #
<u> </u>	<u> ✓ </u>	<u> </u>
<u> </u>	<u> ✓ </u>	<u> </u>

A. Cross-ply cracking in virgin material?

B. Ply lifting?

Record the Nose Cap Char and Erosion Measurements Below:

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
1.5	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
4.0	<u>0.34</u>	<u>0.49</u>	<u>0.36</u>	<u>0.57</u>	<u>0.39</u>	<u>0.51</u>	<u>0.40</u>	<u>0.44</u>
6.0	<u>0.35</u>	<u>0.53</u>	<u>0.35</u>	<u>0.60</u>	<u>0.44</u>	<u>0.51</u>	<u>0.39</u>	<u>0.46</u>
8.0	<u>0.43</u>	<u>0.51</u>	<u>0.41</u>	<u>0.51</u>	<u>0.46</u>	<u>0.50</u>	<u>0.46</u>	<u>0.44</u>
10.0	<u>0.47</u>	<u>0.49</u>	<u>0.43</u>	<u>0.50</u>	<u>0.54</u>	<u>0.46</u>	<u>0.48</u>	<u>0.48</u>
12.0	<u>0.53</u>	<u>0.46</u>	<u>0.51</u>	<u>0.52</u>	<u>0.59</u>	<u>0.45</u>	<u>0.55</u>	<u>0.45</u>
14.0	<u>0.62</u>	<u>0.41</u>	<u>0.58</u>	<u>0.52</u>	<u>0.71</u>	<u>0.39</u>	<u>0.64</u>	<u>0.42</u>
16.0	<u>0.68</u>	<u>0.47</u>	<u>0.67</u>	<u>0.47</u>	<u>0.75</u>	<u>0.41</u>	<u>0.72</u>	<u>0.46</u>
18.0	<u>0.82</u>	<u>0.46</u>	<u>0.75</u>	<u>0.46</u>	<u>0.90</u>	<u>0.46</u>	<u>0.83</u>	<u>0.40</u>
20.0	<u>1.02</u>	<u>0.40</u>	<u>0.97</u>	<u>0.50</u>	<u>1.18</u>	<u>0.37</u>	<u>1.06</u>	<u>0.39</u>
22.0	<u>1.52</u>	<u>0.56</u>	<u>1.45</u>	<u>0.67</u>	<u>1.72</u>	<u>0.51</u>	<u>1.59</u>	<u>0.57</u>
24.0	<u>1.68</u>	<u>0.61</u>	<u>1.64</u>	<u>0.73</u>	<u>1.85</u>	<u>0.61</u>	<u>1.76</u>	<u>0.74</u>
26.0	<u>1.19</u>	<u>0.70</u>	<u>1.18</u>	<u>0.69</u>	<u>1.19</u>	<u>0.68</u>	<u>1.29</u>	<u>0.76</u>

Negative Margin of Safety? Yes ✓ No Station: Degree:

Notes / Comments

Preliminary PFAR(s)? Yes ✓ No Preliminary PFAR Number(s):

Clarification Form(s)? Yes ✓ No Clarification Form Page No.(s):

POSTFLIGHT OBSERVATION RECORD (PFOR) C-18
Forward Nose Ring and Aft Inlet Ring Phenolic (CCP) Section Condition

Motor No.: 360L029	Side: Right (B)	Date: 3/3/93
---------------------------	------------------------	---------------------

Assessment Engineer(s)/Inspector(s): Jim TASSMAN, Larry Wilks

Forward Nose and Aft Inlet Ring Phenolic Section Observations:

	Yes	No	Comment #
A. Cross-ply cracking in virgin material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
B. Ply lifting?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Record the Forward Nose Ring (-503) Char and Erosion Measurements Below:

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
28.0	<u>1.15</u>	<u>0.69</u>	<u>1.08</u>	<u>0.73</u>	<u>1.12</u>	<u>0.59</u>	<u>1.19</u>	<u>0.64</u>
30.0	<u>0.92</u>	<u>0.63</u>	<u>0.92</u>	<u>0.63</u>	<u>0.98</u>	<u>0.63</u>	<u>0.99</u>	<u>0.55</u>
32.0	<u>0.98</u>	<u>0.59</u>	<u>0.95</u>	<u>0.62</u>	<u>1.01</u>	<u>0.60</u>	<u>1.05</u>	<u>0.54</u>

Negative Margin of Safety? ☐ Yes ☒ No Station: _____ Degree: _____

Record the Aft Inlet Ring Char (-504) and Erosion Measurements Below:

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
34.0	<u>0.89</u>	<u>0.58</u>	<u>0.99</u>	<u>0.48</u>	<u>0.94</u>	<u>0.56</u>	<u>0.97</u>	<u>0.53</u>
36.0	<u>0.91</u>	<u>0.59</u>	<u>0.99</u>	<u>0.53</u>	<u>0.97</u>	<u>0.55</u>	<u>0.95</u>	<u>0.55</u>
38.0	<u>0.95</u>	<u>0.60</u>	<u>0.98</u>	<u>0.51</u>	<u>1.01</u>	<u>0.61</u>	<u>0.97</u>	<u>0.51</u>
39.0	<u>0.97</u>	<u>0.67</u>	<u>1.01</u>	<u>0.62</u>	<u>1.04</u>	<u>0.59</u>	<u>0.99</u>	<u>0.56</u>

Negative Margin of Safety? ☐ Yes ☒ No Station: _____ Degree: _____

Notes / Comments

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): _____

Clarification Form(s)? ☐ Yes ☒ No Clarification Form Page No.(s): _____

V. K. Henson, SA51
E613/RMP-FY94-181

Distribution

M. Davis, EE54
R. B. Roth, TC/MSFC
E. Skrobiszewski, RMO/K68
L. Metts, CP11
M. Hill, ED64
V. Richards, ED24
R. McIntosh, EH31
B. Goldberg, EP54
J. Redus, EP51
D. Dugal, RIC (2)
R. Green, RIC
Library-D, KSC (2)
Tech Data Center, KSC USBI/QA-2
Central Documentation Repository, CN22D (7)